



**AUDI A3: 1FLX261**

Vinnumber:	<b>WAUZZZ8V9EA034972</b>	Versionname:	<b>A3 SB Attraction S-tr.105PK Aut.</b>
First Registrationdate:	<b>12/08/2013</b>	Fiscalpower:	
Expertise Mileage:	<b>100347</b>	Power Kw:	<b>77</b>
Bodytype:		Body color:	<b>White</b>
Gearbox:	<b>Automatic</b>	Paint type:	<b>Metallic</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Maintenance:	<b>19600</b>	Parking lot:	<b>2630</b>
Maintenance:	<b>393 DAGEN</b>		
Maintenance:	<b>OK</b>		
Battery functioning:	<b>Yes</b>		
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		

**Options**

Radio CD		Sun Roof electric	
GPS storage	<b>SD</b>	Panoramic roof	
GPS storage		Central consol F	
Windows electric F		Luggage cover	
Windows electric R		Rear parking sensors	
Cruise Control			
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	<b>Headlighting Halogen</b>		
Type of GPS	<b>GPS big screen color</b>		
Type of Lining	<b>Lining leather</b>		
Type of climate control	<b>Autom climate control</b>		

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

	<b>205/55/16/91 W LightMetal</b>			
Summer tyres:	Fr.L.	<b>Continental: 4 mm</b>	Fr.R.	<b>Continental: 4 mm</b>
	Re.L.	<b>Continental: 5 mm</b>	Re.R.	<b>Continental: 5 mm</b>

**Assistance equipment**

Repair kit	<b>Yes</b>	Compressor	<b>Yes</b>
------------	------------	------------	------------

Total cost ex VAT	<b>425,80</b>
-------------------	---------------

Sill trim R L, Scratch(es), Acceptable	<b>0,00</b>
--	-------------

*No pictures to display*

Alloy rim F L, Scratch(es), Acceptable	<b>0,00</b>
--	-------------

*No pictures to display*

Alloy rim R R, Scratch(es), LI - Repair and paint (complete)	<b>95,00</b>
--	--------------

*No pictures to display*





Windscreen, Stone chip(s), Windscreen repair 0,00



Wing R L, Dent(s) and scratch(es), Acceptable 0,00

*No pictures to display*

Trunk lid covering R, Scratch(es), Acceptable 0,00

*No pictures to display*

Sill trim R R, Scratch(es), Acceptable 0,00

*No pictures to display*

Bonnet, Stone chip(s), Acceptable 0,00

*No pictures to display*

Alloy rim F R, Scratch(es), LI - Repair and paint (complete) 95,00



Bumper R, Scratch(es), Acceptable 0,00

*No pictures to display*

Internal Boot Lining L, Scratch(es), Acceptable 0,00

*No pictures to display*

Rear bulkhead lining, Scratch(es), Acceptable 0,00

*No pictures to display*

Outer backrest protection L, Scratch(es), Acceptable 0,00

*No pictures to display*

Outer backrest protection R, Scratch(es), Acceptable 0,00

*No pictures to display*

Internal Boot Lining R, Scratch(es), Acceptable 0,00

*No pictures to display*

Wing F L, Scratch(es), Acceptable 0,00

*No pictures to display*

Seat F L compl, Worn, Acceptable 0,00



Front bumper, Scratch(es), LI - Repair and paint (complete) 235,80



