



| AUDI A3: 1HAU126 | | | |
|------------------------------------|-------------------------|--------------|-------------------------------|
| Vinnnumber: | WAUZZ8V2EA171963 | Versionname: | A3 SB Ultra Attraction |
| First Registrationdate: | 5/06/2014 | Fiscalpower: | 110PK |
| Expertise Mileage: | 136854 | Power Kw: | 81 |
| Bodytype: | Hatchback | Body color: | Silver |
| Gearbox: | MAN 6 VIT | Paint type: | Metalic |
| Transmission: | | Rims summer: | Aluminium |
| Fueltype: | Diesel | Oil level: | OK |
| Battery functioning: | Yes | Parking lot: | 3333 |
| Number of doors: | 5 | | |
| Number of seats: | 5 | | |
| Number head rests: | 5 | | |
| Rims summer: | Aluminium | | |
| Category: | Passenger Car | | |
| Oil level: | OK | | |
| Registration Certificate Car (BE): | Yes | | |

| Options | | | |
|--------------------------------|------------------------------|----------------------|-------------------|
| Radio CD | | Central consol F | |
| Windows electric F | | Luggage cover | |
| Windows electric R | | Rear parking sensors | |
| Cruise Control | | Type of Tow bar | No Tow bar |
| Steering wheel multifunctional | | | |
| Seats F heated | | | |
| Radio multimedia | | | |
| Type of headlighting | Headlighting Halogen | | |
| Type of GPS | GPS big screen color | | |
| Type of Lining | Lining leather | | |
| Type of climate control | Autom climate control | | |

| Limited Technical Inspection | | | |
|------------------------------|-----------|---------------------|------------|
| Airco functioning | OK | Battery functioning | Yes |
| Tires wear profile | OK | Power steering | Yes |
| Idle position | OK | Sound engine | OK |
| Engine startingtime | OK | Clutch test | OK |
| Exhaust gass | OK | Wiper fluid level | OK |
| Handbrake | OK | Transmission | OK |
| | | Lighting | OK |
| | | Wiperblades | OK |

| Degree of wear | | | | |
|----------------|----------------------------------|-----------------------|-------|-----------------------|
| | 205/55/16/91 H LightMetal | | | |
| Summer tyres: | Fr.L. | Kleber: 5 mm | Fr.R. | Kleber: 5 mm |
| | Re.L. | Uniroyal: 5 mm | Re.R. | Uniroyal: 5 mm |

| Assistance equipment | | | |
|---|------------|------------|---------------|
| Repair kit | Yes | Compressor | Yes |
| Total cost ex VAT | | | 540,00 |
| Wing F R, Scratch(es), Acceptable | | | 0,00 |
| <i>No pictures to display</i> | | | |
| Wing R R, Dent(s) and scratch(es), LI - Repair and paint (complete) | | | 308,20 |





| | |
|---|------|
| Bumper R, Dent(s) and scratch(es), Acceptable | 0,00 |
|---|------|

No pictures to display

| | |
|---|--------|
| Front bumper, Scratch(es), LI - Repair and paint (complete) | 211,80 |
|---|--------|



| | |
|-----------------------------------|-------|
| Boot carpet, Damaged, E - Replace | 20,00 |
|-----------------------------------|-------|

