


**BMW 5: 1JFJ103**

Vinnumber:	<b>WBA5L31040G118067</b>	Versionname:	<b>5 TOURING 520d 163PK</b>
First Registrationdate:	<b>3/12/2014</b>	Fiscalpower:	
Expertise Mileage:	<b>174232</b>	Power Kw:	<b>120</b>
Bodytype:	<b>Break</b>	Body color:	<b>Black</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Back</b>	Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>4705</b>
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

**Options**

Radio CD	Central consol F
Windows electric F	Luggage cover
Windows electric R	Front parking sensors
Cruise Control	Rear parking sensors
Steering wheel multifunctional	
Seats F heated	
Radio multimedia	
Type of headlighting:	<b>Headlighting Xenon</b>
Type of GPS:	<b>GPS big screen color</b>
Type of Lining:	<b>Lining leather</b>
Type of climate control:	<b>Autom climate control</b>

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

<b>225/55/17/97 Y LightMetal</b>				
Summer tyres:	Fr.L.	Michelin: 4 mm	Fr.R.	Michelin: 4 mm
	Re.L.	Michelin: 4 mm	Re.R.	Michelin: 4 mm

**Assistance equipment**

Repair kit	<b>Yes</b>	Compressor	<b>Yes</b>
Total cost ex VAT			404,16
Alloy rim F R, Scratch(es), Acceptable			0,00
<i>No pictures to display</i>			
Bonnet, Dent(s) and scratch(es), Acceptable			0,00
<i>No pictures to display</i>			
Bumper R, Dent(s) and scratch(es), Acceptable			0,00
<i>No pictures to display</i>			
Alloy rim R L, Scratch(es), Acceptable			0,00
<i>No pictures to display</i>			
Front bumper, Scratch(es), Acceptable			0,00
<i>No pictures to display</i>			
Front bumper, Scratch(es), LI - Repair and paint (complete)			254,16



Door R L, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Door F L, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Ignition key, Missing, E - Replace	150,00
<i>No pictures to display</i>	