



CITROEN C4 PICASSO: 1GRP441

Vinnnumber:	VF73D9HC8EJ620676	Versionname:	
First Registrationdate:	9/04/2014	Fiscalpower:	
Expertise Mileage:	91080	Power Kw:	85
Bodytype:		Body color:	Grey
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:		Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	3326
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD	Central consol F	
Windows electric F	Rear parking sensors	
Windows electric R	Type of Tow bar	No Tow bar
Cruise Control		
Steering wheel multifunctional		
Radio multimedia		
Type of headlighting	Headlighting Halogen	
Type of GPS	GPS big screen color	
Type of Lining	Lining fabrics	
Type of climate control	Autom climate control	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	205/60/16/96 H LightMetal			
Winter tyres:	Fr.L.	Uniroyal: 7 mm	Fr.R.	Uniroyal: 7 mm
	Re.L.	Michelin: 6 mm	Re.R.	Michelin: 6 mm

Assistance equipment










Total cost ex VAT	976,30
Alloy rim F L, Scratch(es), LI - Repair and paint (complete)	95,00



Door R L, Dent(s), Acceptable	0,00
-------------------------------	------

No pictures to display

Door F L, Scratch(es), Acceptable	0,00
-----------------------------------	------

Door L, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Protection plate M, Tear, E - Replace	74,00
	
Alloy rim F R, Scratch(es), LI - Repair and paint (complete)	95,00
	
	
Alloy rim R L, Scratch(es), LI - Repair and paint (complete)	95,00
	
	
Maintenance book, Missing, E - Replace	0,00
<i>No pictures to display</i>	
Bumper R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Door R R, Dent(s), Acceptable	0,00
<i>No pictures to display</i>	
Wing F L, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Alloy rim R R, Scratch(es), LI - Repair and paint (complete)	95,00
	
	
Front bumper, Dent(s) and scratch(es), LI - Repair and paint (complete)	211,80
	
	
Sill outer R, Dent(s) and scratch(es), LI - Repair and paint (complete)	310,50

