



|                         |                          |              |                             |
|-------------------------|--------------------------|--------------|-----------------------------|
| <b>BMW 3: 1FLU164</b>   |                          |              |                             |
| Vinnnumber:             | <b>WBA3K91010F930915</b> | Versionname: | <b>3 TOURING 316d 116PK</b> |
| First Registrationdate: | <b>9/08/2013</b>         | Fiscalpower: |                             |
| Expertise Mileage:      | <b>91688</b>             | Power Kw:    | <b>85</b>                   |
| Bodytype:               | <b>Break</b>             | Body color:  | <b>Grey</b>                 |
| Gearbox:                | <b>MAN 6 VIT</b>         | Paint type:  | <b>Metalic</b>              |
| Transmission:           |                          | Rims summer: | <b>Aluminium</b>            |
| Fueltype:               | <b>Diesel</b>            | Oil level:   | <b>OK</b>                   |
| Battery functioning:    | <b>Yes</b>               | Parking lot: | <b>2515</b>                 |
| Number of doors:        | <b>5</b>                 |              |                             |
| Number of seats:        | <b>5</b>                 |              |                             |
| Number head rests:      | <b>5</b>                 |              |                             |
| Rims summer:            | <b>Aluminium</b>         |              |                             |
| Category:               | <b>Passenger Car</b>     |              |                             |
| Oil level:              | <b>OK</b>                |              |                             |

|                                |                              |                      |                      |
|--------------------------------|------------------------------|----------------------|----------------------|
| <b>Options</b>                 |                              |                      |                      |
| Radio CD                       |                              | Central consol F     |                      |
| Windows electric F             |                              | Luggage cover        |                      |
| Windows electric R             |                              | Rear parking sensors |                      |
| Cruise Control                 |                              | Type of Tow bar      | <b>Tow bar fixed</b> |
| Steering wheel multifunctional |                              |                      |                      |
| Type of headlighting           | <b>Headlighting Halogen</b>  |                      |                      |
| Type of GPS                    | <b>No GPS</b>                |                      |                      |
| Type of Lining                 | <b>Lining fabrics</b>        |                      |                      |
| Type of climate control        | <b>Autom climate control</b> |                      |                      |

|                                     |           |                     |            |
|-------------------------------------|-----------|---------------------|------------|
| <b>Limited Technical Inspection</b> |           |                     |            |
| Airco functioning                   | <b>OK</b> | Battery functioning | <b>Yes</b> |
| Tires wear profile                  | <b>OK</b> | Power steering      | <b>Yes</b> |
| Idle position                       | <b>OK</b> | Sound engine        | <b>OK</b>  |
| Engine startingtime                 | <b>OK</b> | Clutch test         | <b>OK</b>  |
| Exhaust gass                        | <b>OK</b> | Wiper fluid level   | <b>OK</b>  |
| Handbrake                           | <b>OK</b> | Transmission        | <b>OK</b>  |
|                                     |           | Lighting            | <b>OK</b>  |
|                                     |           | Wiperblades         | <b>OK</b>  |

|                       |                                  |                       |       |                       |
|-----------------------|----------------------------------|-----------------------|-------|-----------------------|
| <b>Degree of wear</b> |                                  |                       |       |                       |
|                       | <b>205/60/16/96 V LightMetal</b> |                       |       |                       |
| Summer tyres:         | Fr.L.                            | <b>Uniroyal: 6 mm</b> | Fr.R. | <b>Uniroyal: 6 mm</b> |
|                       | Re.L.                            | <b>Uniroyal: 6 mm</b> | Re.R. | <b>Uniroyal: 6 mm</b> |

|                             |            |            |            |
|-----------------------------|------------|------------|------------|
| <b>Assistance equipment</b> |            |            |            |
| Repair kit                  | <b>Yes</b> | Compressor | <b>Yes</b> |

|   |               |
|---|---------------|
| <b>Total cost ex VAT</b>  | <b>385,08</b> |
| <b>Alloy rim R R, Scratch(es), LI - Repair and paint (complete)</b> | <b>95,00</b>  |



|  |               |
|--|---------------|
| <b>Door R L, Scratch(es), Acceptable</b>                           | <b>0,00</b>   |
| <i>No pictures to display</i>                                      |               |
| <b>Bonnet, Chemical polution, LI - Repair and paint (complete)</b> | <b>290,08</b> |



|  |      |
|--|------|
| Door F R, Scratch(es), Acceptable      | 0,00 |
| <i>No pictures to display</i>          |      |
| Alloy rim F R, Scratch(es), Acceptable | 0,00 |
| <i>No pictures to display</i>          |      |