



BMW 4 GRAN COUPE: 1LCH883

Vinnumber:	WBA4E710X0GR81128	Versionname:	2.0 418D (110KW) GRAN COUPE
First Registrationdate:	19/08/2015	Fiscalpower:	
Expertise Mileage:	143577	Power Kw:	110
Bodytype:	Berline	Body color:	Dark Grey
Gearbox:	Automatic	Paint type:	Metalic
Transmission:	Back	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	2126
Number of doors:	5		
Number of seats:	5		
Number head rests:	4		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD	Central consol F	
Windows electric F	Rear parking sensors	
Windows electric R	Type of Tow bar	No Tow bar
Cruise Control		
Steering wheel multifunctional		
Radio multimedia		
Type of headlighting	Headlighting Xenon	
Type of GPS	GPS big screen color	
Type of Lining	Lining leather	
Type of climate control	Autom climate control	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	225/45/18/91 Y LightMetal			
Summer tyres:	Fr.L.	Continental: 3 mm	Fr.R.	Continental: 3 mm
	Re.L.	Continental: 5 mm	Re.R.	Continental: 5 mm

Assistance equipment

Total cost ex VAT	1288,98
Bumper R, Scratch(es), LI - Repair and paint (complete)	254,16




Front bumper, Dent(s) and scratch(es), Acceptable 0,00





Roof, Chemical pollution, LI - Repair and paint (complete) 577,80



Tailgate, Scratch(es), LI - Repair and paint (complete) 362,02



Alloy rim F R, Scratch(es), LI - Repair and paint (complete) 95,00



Wing R R, Dent(s), Acceptable 0,00

No pictures to display