



BMW 1 HATCH: 1LDH641			
Vinnnumber:	WBA1V910605B19103	Versionname:	1.5 116D EFFICIENTDYNAMICS EDIT. (85KW)
First Registrationdate:	27/08/2015	Expertise Mileage:	48090
Bodytype:	Hatchback	Fiscalpower:	85
Gearbox:	MAN 6 VIT	Power Kw:	85
Transmission:		Body color:	Dark Blue
Fueltype:	Diesel	Paint type:	Metalic
Battery functioning:	Yes	Rims summer:	Aluminium
Number of doors:	5	Oil level:	OK
Number of seats:	5	Parking lot:	1105
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options			
Radio CD		Central consol F	
Windows electric F		Luggage cover	
Windows electric R		Rear parking sensors	
Cruise Control		Type of Tow bar	No Tow bar
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Autom climate control		

Limited Technical Inspection			
Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear			
Winter tyres:	205/55/16/91 H LightMetal		
	Fr.L.	Fr.R.	Michelin: 7 mm
	Re.L.	Re.R.	Michelin: 6 mm

Assistance equipment			
Repair kit	Yes	Compressor	Yes

Total cost ex VAT	591,15
Door R R, Dent(s), PDR - Knock out without painting	82,80



Door F L, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Alloy rim F R, Scratch(es), LI - Repair and paint (complete)	95,00




Alloy rim R R, Scratch(es), LI - Repair and paint (complete) 95,00



Door R L, Dent(s), Acceptable 0,00

No pictures to display

Door F R, Dent(s), LI - Repair and paint (complete) 318,35



Wing R R, Dent(s), Acceptable 0,00

No pictures to display