


**BMW 3: 1GED665**

Vinnumber:	<b>WBA3D91000J412821</b>	Versionname:	<b>3 BER 316d 116PK</b>
First Registrationdate:	<b>14/01/2014</b>	Fiscalpower:	
Expertise Mileage:	<b>63204</b>	Power Kw:	<b>85</b>
Bodytype:		Body color:	<b>Brown</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Back</b>	Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Maintenance:	<b>6000 KM OVERSCHREDEN</b>	Parking lot:	<b>4721</b>
Maintenance:	<b>NOT OK</b>		
Battery functioning:	<b>Yes</b>		
Number of doors:	<b>4</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

**Options**

Radio CD	Central consol F
GPS storage	<b>HD</b>
GPS storage	
Windows electric F	
Windows electric R	
Cruise Control	
Steering wheel multifunctional	
Radio multimedia	
Type of headlighting	<b>Headlighting Halogen</b>
Type of GPS	<b>GPS big screen color</b>
Type of Lining	<b>Lining artificial leather</b>
Type of climate control	<b>Manual climate control</b>

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>











**Degree of wear**

	<b>205/60/16/92 H LightMetal</b>			
Winter tyres:	Fr.L.	<b>Michelin: 4 mm</b>	Fr.R.	<b>Michelin: 4 mm</b>
	Re.L.	<b>Michelin: 4 mm</b>	Re.R.	<b>Michelin: 4 mm</b>

**Assistance equipment**

Repair kit	<b>Yes</b>	Compressor	<b>Yes</b>
Total cost ex VAT			<b>586,20</b>
Door R R, Repaired, Acceptable			<b>0,00</b>


**Wing R R, Repaired, No repair**
**0,00**

	Door R R, Dent(s), Acceptable	0,00
	Bumper R, Scratch(es), Acceptable	0,00
	Door R L, Dent(s) and scratch(es), Acceptable	0,00
	Bumper F R, Scratch(es), It - Spot repair	115,56
	Seat cover F L, Worn, Acceptable	0,00
	Door panel F R, Hole, Smart repair	110,64
	Seat cover R L, Tear, E - Replace	360,00
	Door panel F R, Hole, Smart repair	110,64
	Seat cover R L, Tear, E - Replace	360,00
	Seat cover R L, Tear, E - Replace	360,00



Door F L, Scratch(es), Acceptable 0,00

