



AUDI A6: 1GTF494

Vinnumber:	WAUZZ4GXEN143845	Versionname:	A6 AVANT 136PK
First Registrationdate:	23/04/2014	Fiscalpower:	
Expertise Mileage:	89611	Power Kw:	100
Bodytype:	Break	Body color:	Grey
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OK	Parking lot:	3305
Maintenance	dans 4600 KM		
Battery functioning	Yes		
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	Yes		

Options

Radio CD		Central consol F
GPS storage		Luggage cover
GPS storage	HD	Front parking sensors
Windows electric F		Rear parking sensors
Windows electric R		
Cruise Control		
Steering wheel multifunctional		
Seats F heated		
Radio multimedia		
Type of headlighting	Headlighting Halogen	
Type of GPS	GPS big screen color	
Type of Lining	Lining leather	
Type of climate control	Autom climate control	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	225/60/16/102 W LightMetal			
Summer tyres:	Fr.L.	Kleber: 4 mm	Fr.R.	Kleber: 4 mm
	Re.L.	Kleber: 4 mm	Re.R.	Kleber: 4 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	2024,85
Door F R, Scratch(es), LI - Repair and paint (complete)	382,02



Sill outer R, Scratch(es), LI - Repair and paint (complete)	372,60
---	--------



Door R R, Scratch(es), LI - Repair and paint (complete)

382,02



Wing R R, Dent(s) and scratch(es), LI - Repair and paint (complete)

369,84



Wing F R, Scratch(es), LI - Repair and paint (complete)

264,21



Bonnet, Scratch(es), 67 - Polish

0,00



Step R, Scratch(es), Acceptable

0,00



Bumper R, Scratch(es), 67 - Polish

0,00



Rearview mirror housing R, Scratch(es), Acceptable

0,00



Alloy rim F R, Scratch(es), Acceptable

0,00



Front bumper, Scratch(es), LI - Repair and paint (complete)

254,16

