


BMW 5: 1EXQ768

Vinnnumber:	WBAFW91060DW48427	Versionname:	5 BER 520d
First Registrationdate:	16/04/2013	Fiscalpower:	Eff.Dyn.Ed.St/Stp 163PK
Expertise Mileage:	159968	Power Kw:	120
Bodytype:		Body color	Dark Grey
Gearbox:	MAN 6 VIT	Paint type	Metalic
Transmission:		Rims summer	Aluminium
Fueltype:	Diesel	Oil level	OK
Battery functioning	Yes	Parking lot	3303
Number of doors	4		
Number of seats	5		
Number head rests	5		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		

Options

Radio CD	Central consol F
Windows electric F	Front parking sensors
Windows electric R	Rear parking sensors
Cruise Control	Type of Tow bar
Steering wheel multifunctional	No Tow bar
Radio multimedia	
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining leather
Type of climate control	Autom climate control
Head-up Display	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	225/55/17/97 H LightMetal			
Winter tyres:	Fr.L.	Pirelli: 3 mm	Fr.R.	Pirelli: 3 mm
	Re.L.	Pirelli: 2 mm	Re.R.	Pirelli: 2 mm

Assistance equipment

	Runflat	Yes
Total cost ex VAT		1124,34
Door F R, Scratch(es), Acceptable		0,00
<i>No pictures to display</i>		
Wing F R, Scratch(es), Acceptable		0,00
<i>No pictures to display</i>		
Door F L, Scratch(es), Acceptable		0,00
<i>No pictures to display</i>		
Door R L, Scratch(es), LI - Repair and paint (complete)		382,02





Sill outer L, Scratch(es), LI - Repair and paint (complete)

372,60



Bumper R, Dent(s) and scratch(es), LI - Repair and paint (complete)

254,16



Tailgate, Bad repair, Acceptable

0,00



Door frame F R, Dent(s), It - Spot repair

115,56

