



BMW 5 TOURING: 1GUM135

Vinnumber:	WBADR71010GV68955	Versionname:	520d Touring
First Registrationdate:	1/04/2004	Fiscalpower:	
Expertise Mileage:	296889	Power Kw:	100
Bodytype:	Break	Body color:	Silver
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Back	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	3619
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Central consol F	
Windows electric F		Luggage cover	
Windows electric R		Type of Tow bar	Tow bar fixed
Cruise Control			
Steering wheel multifunctional			
Type of headlighting	Headlighting Halogen		
Type of GPS	No GPS		
Type of Lining	Lining leather		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

225/55/16/99 Y LightMetal				
Summer tyres:	Fr.L.	Continental: 5 mm	Fr.R.	Continental: 5 mm
	Re.L.	Continental: 5 mm	Re.R.	Continental: 5 mm
225/55/16/99 H LightMetal				
Winter tyres:	Fr.L.	Continental: 4 mm	Fr.R.	Continental: 4 mm
	Re.L.	Continental: 6 mm	Re.R.	Continental: 6 mm

Assistance equipment

Spare wheel	Yes	Jack	Yes
-------------	------------	------	------------

Total cost ex VAT	1708,47
Wing R L, Rust, It - Spot repair	115,56



Steering wheel, Worn, Acceptable	0,00
----------------------------------	-------------

No pictures to display

Rearview mirror basis R, Bad repair, Acceptable	0,00
---	-------------

No pictures to display

Rearview mirror housing R, Scratch(es), Acceptable	0,00
--	-------------

No pictures to display

No pictures to display

Door F L, Rust, LI - Repair and paint (complete) 382,02



Bonnet, Rust, LI - Repair and paint (complete) 348,09



Bumper R, Scratch(es), Acceptable 0,00

No pictures to display

Front bumper, Crack, Le - Replace and paint 862,80



Wing R R, Rust, Acceptable 0,00

No pictures to display