



FORD Fiesta: 1FMR219

Vinnumber:	WF0DXXGAKDDM06054	Versionname:	FIESTA BER Trend PowerShift 105PK Aut.
First Registrationdate:	21/08/2013	Fiscalpower:	
Expertise Mileage:	17856	Power Kw:	77
Bodytype:	Hatchback	Body color:	Silver
Gearbox:	Automatic	Paint type:	Metalic
Transmission:	Front	Rims summer:	Steel
Fueltype:	Petrol	Oil level:	OK
Battery functioning:	Yes	Parking lot:	3825
Number of doors:	5		
Number of seats:	5		
Number head rests:	4		
Rims summer:	Steel		
Category:	Passenger Car		
Oil level:	OK		

Options

Radio CD	Luggage cover
Windows electric F	
Steering wheel multifunctional	
Radio multimedia	
Type of headlighting	Headlighting Halogen
Type of GPS	No GPS
Type of Lining	Lining fabrics
Type of climate control	Autom climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	195/50/15/82 H Steel			
Summer tyres:	Fr.L.	Hankook: 5 mm	Fr.R.	Hankook: 5 mm
	Re.L.	Hankook: 6 mm	Re.R.	Hankook: 6 mm

Assistance equipment

Spare wheel	Yes	Jack	Yes
-------------	------------	------	------------

Total cost ex VAT	951,56
-------------------	---------------

Door R L, Scratch(es), LI - Repair and paint (complete)	0,00
---------------------------------------------------------	-------------



Tailgate, Dent(s), PDR - Knock out without painting	63,00
-----------------------------------------------------	--------------



Door F L, Scratch(es), LI - Repair and paint (complete)	254,68
---------------------------------------------------------	---------------



Front bumper, Scratch(es), LI - Repair and paint (complete) 169,44



Wheel cover F R, Scratch(es), E - Replace 24,00



Rearlight R , Broken, E - Replace 96,00



Wheel cover F L, Scratch(es), Acceptable 0,00

No pictures to display

Ignition key, Missing, E - Replace 150,00

No pictures to display

Bumper R, Scratch(es), LI - Repair and paint (complete) 194,44

