


FORD Galaxy: 1GFU457

Vinnnumber:	WF0MXXGBWMDE02764	Versionname:	GALAXY Trend Style St/St
First Registrationdate:	28/01/2014	Fiscalpower:	DPF 115PK
Expertise Mileage:	77415	Power Kw:	85
Bodytype:		Body color:	Grey
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OK	Parking lot:	2528
Maintenance:	GEEN MELDING		
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	7		
Number head rests:	7		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Seats electric F L
GPS storage		Central consol F
GPS storage	HD	Luggage cover
Windows electric F		Front parking sensors
Windows electric R		Rear parking sensors
Cruise Control		
Steering wheel multifunctional		
Radio multimedia		
Type of headlighting	Headlighting Halogen	
Type of GPS	GPS big screen color	
Type of Lining	Lining fabrics	
Type of climate control	Autom climate control	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	215/60/16/99 H LightMetal			
Summer tyres:	Fr.L.	Michelin: 3 mm	Fr.R.	Michelin: 3 mm
	Re.L.	Michelin: 3 mm	Re.R.	Michelin: 4 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
Total cost ex VAT			796,05
Seat cover R, Worn, Acceptable			0,00

No pictures to display

Wing F L, Dent(s), LI - Repair and paint (complete)	312,21
---	---------------



Front bumper, Scratch(es), Acceptable	0,00
---------------------------------------	-------------

No pictures to display

Door F L, Dent(s) and scratch(es), Acceptable	0,00
---	------

No pictures to display

Bumper R, Dent(s) and scratch(es), E - Replace	483,84
--	--------



Bonnet, Scratch(es), Acceptable	0,00
---------------------------------	------

No pictures to display

Door trim F L, Scratch(es), Acceptable	0,00
--	------

No pictures to display

Seat cover F R, Worn, Acceptable	0,00
----------------------------------	------

No pictures to display

Door R L, Repaired, Acceptable	0,00
--------------------------------	------

No pictures to display

Wing R R, Repaired, No repair	0,00
-------------------------------	------

No pictures to display

Door R R, Repaired, Acceptable	0,00
--------------------------------	------

No pictures to display

Wing R L, Repaired, No repair	0,00
-------------------------------	------

No pictures to display