



CITROEN C4 Picasso: 1FJK050

Vinnumber:	VF7UA9HR8DJ703860	Versionname:	GR.C4 PICAS. e-HDi
First Registrationdate:	16/07/2013	Fiscalpower:	Bus.GPS FAP BMP 112PK
Expertise Mileage:	100532	Power Kw:	82
Bodytype:	Break	Body color:	Blue
Gearbox:	Automatic	Paint type:	Metalic
Transmission:	Back	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	4727
Number of doors:	5		
Number of seats:	7		
Number head rests:	7		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		

Options

Radio CD	Luggage cover	
Windows electric F	Rear parking sensors	
Windows electric R	Type of Tow bar	No Tow bar
Cruise Control		
Steering wheel multifunctional		
Radio multimedia		
Type of headlighting	Headlighting Halogen	
Type of GPS	GPS big screen color	
Type of Lining	Lining fabrics	
Type of climate control	Autom climate control	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	215/55/16/93 V LightMetal			
Summer tyres:	Fr.L.	Michelin: 3 mm	Fr.R.	Michelin: 3 mm
	Re.L.	Michelin: 4 mm	Re.R.	Michelin: 4 mm

Assistance equipment

Emergency spare wheel	Yes	Jack	Yes
-----------------------	------------	------	------------

Total cost ex VAT	1870,91
-------------------	----------------







Door R R, Scratch(es), LI - Repair and paint (complete)	318,35
---	---------------



Wing R L, Scratch(es), LI - Repair and paint (complete)	308,20
---	---------------



Rearview mirror housing R, Scratch(es), Acceptable	0,00
--	-------------

<i>No pictures to display</i>		
Door R L, Scratch(es), Acceptable		0,00
<i>No pictures to display</i>		
Bumper R, Scratch(es), LI - Repair and paint (complete)		211,80
		
		
Wing F R, Scratch(es), LI - Repair and paint (complete)		220,18
		
Wing R R, Scratch(es), Acceptable		0,00
<i>No pictures to display</i>		
Sill outer R, Dent(s) and scratch(es), LI - Repair and paint (complete)		310,50
		
Roof, Dent(s), Acceptable		0,00
<i>No pictures to display</i>		
Front bumper, Scratch(es), LI - Repair and paint (complete)		211,80
		
Bonnet, Chemical polution, LI - Repair and paint (complete)		290,08
		
Door F L, Scratch(es), Acceptable		0,00
<i>No pictures to display</i>		