



FORD Mondeo: 1FXT818

Vinnumber:	WFOGXXGBBGDC71886	Versionname:	
First Registrationdate:	2/12/2013	Fiscalpower:	
Expertise Mileage:	151505	Power Kw:	85
Bodytype:		Body color:	Grey
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	2807
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Central consol F	
GPS storage		Luggage cover	
GPS storage	SD	Front parking sensors	
Windows electric F		Rear parking sensors	
Windows electric R		Type of Tow bar	Tow bar removable
Cruise Control			
Steering wheel multifunctional			
Seats F heated			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining leather		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	215/55/16/93 H LightMetal			
Summer tyres:	Fr.L.	Continental: 5 mm	Fr.R.	Continental: 5 mm
	Re.L.	Michelin: 4 mm	Re.R.	Michelin: 4 mm










Assistance equipment

Spare wheel	Yes	Jack	Yes
-------------	------------	------	------------

Total cost ex VAT	2510,05
-------------------	----------------

Door R L, Scratch(es), LI - Repair and paint (complete)	318,35
---	---------------



Bumper R, Dent(s) and scratch(es), LI - Repair and paint (complete)	259,80
	
Bodywork, Damaged, Acceptable	0,00
	
Sill outer L, Dent(s) and scratch(es), LI - Repair and paint (complete)	550,50
	
Wing F L, Dent(s), LI - Repair and paint (complete)	268,18
	
Seat cover F L, Scratch(es), E - Replace	360,00
	
Bodywork, Repaired, P - Check	0,00
	
Wing R L, Scratch(es), LI - Repair and paint (complete)	308,20
	
Door F L, Dent(s), PDR - Knock out without painting	82,80
	
Bumper moulding R, Dent(s), E - Replace	103,66
	
Alloy rim R L, Scratch(es), LI - Repair and paint (complete)	95,00
	
Rear spoiler, Dent(s), LI - Repair and paint (complete)	163,56

