


**MERCEDES CLA: 1HKR988**

|                         |                          |              |                              |
|-------------------------|--------------------------|--------------|------------------------------|
| Vinnumber:              | <b>WDD1173121N122696</b> | Versionname: | <b>CLA BER 180 CDI 109PK</b> |
| First Registrationdate: | <b>12/08/2014</b>        | Fiscalpower: |                              |
| Expertise Mileage:      | <b>101957</b>            | Power Kw:    | <b>80</b>                    |
| Bodytype:               | <b>Berline</b>           | Body color:  | <b>Grey</b>                  |
| Gearbox:                | <b>MAN 6 VIT</b>         | Paint type:  | <b>Metalic</b>               |
| Transmission:           | <b>Back</b>              | Rims summer: | <b>Aluminium</b>             |
| Fueltype:               | <b>Diesel</b>            | Oil level:   | <b>OK</b>                    |
| Battery functioning:    | <b>Yes</b>               | Parking lot: | <b>2814</b>                  |
| Number of doors:        | <b>4</b>                 |              |                              |
| Number of seats:        | <b>5</b>                 |              |                              |
| Number head rests:      | <b>5</b>                 |              |                              |
| Rims summer:            | <b>Aluminium</b>         |              |                              |
| Category:               | <b>Passenger Car</b>     |              |                              |
| Oil level:              | <b>OK</b>                |              |                              |

**Options**

|                                |                                       |
|--------------------------------|---------------------------------------|
| Radio CD                       | Sun Roof electric                     |
| GPS storage                    | Central consol F                      |
| Windows electric F             |                                       |
| Windows electric R             |                                       |
| Steering wheel multifunctional |                                       |
| Radio multimedia               |                                       |
| Type of headlighting           | <b>Headlighting Halogen</b>           |
| Type of GPS                    | <b>GPS big screen color</b>           |
| Type of Lining                 | <b>Lining semi-artificial leather</b> |
| Type of climate control        | <b>Manual climate control</b>         |

**Limited Technical Inspection**

|                     |           |                     |            |
|---------------------|-----------|---------------------|------------|
| Airco functioning   | <b>OK</b> | Battery functioning | <b>Yes</b> |
| Tires wear profile  | <b>OK</b> | Power steering      | <b>Yes</b> |
| Idle position       | <b>OK</b> | Sound engine        | <b>OK</b>  |
| Engine startingtime | <b>OK</b> | Clutch test         | <b>OK</b>  |
| Exhaust gass        | <b>OK</b> | Wiper fluid level   | <b>OK</b>  |
| Handbrake           | <b>OK</b> | Transmission        | <b>OK</b>  |
|                     |           | Lighting            | <b>OK</b>  |
|                     |           | Wiperblades         | <b>OK</b>  |

**Degree of wear**

|               |                                  |                          |       |                          |
|---------------|----------------------------------|--------------------------|-------|--------------------------|
|               | <b>205/55/16/91 H LightMetal</b> |                          |       |                          |
| Winter tyres: | Fr.L.                            | <b>Bridgestone: 6 mm</b> | Fr.R. | <b>Bridgestone: 6 mm</b> |
|               | Re.L.                            | <b>Bridgestone: 5 mm</b> | Re.R. | <b>Bridgestone: 5 mm</b> |

**Assistance equipment**

|            |            |            |            |
|------------|------------|------------|------------|
| Repair kit | <b>Yes</b> | Compressor | <b>Yes</b> |
|------------|------------|------------|------------|

|                   |      |
|-------------------|------|
| Total cost ex VAT | 0,00 |
|-------------------|------|

|                                       |      |
|---------------------------------------|------|
| Front bumper, Scratch(es), Acceptable | 0,00 |
|---------------------------------------|------|

*No pictures to display*

|                                   |      |
|-----------------------------------|------|
| Bumper R, Scratch(es), Acceptable | 0,00 |
|-----------------------------------|------|

*No pictures to display*