



BMW X3: 1HHH302			
Vinnnumber:	WBAWZ310100F63428	Versionname:	X3 2.0d sDrive18 136PK
First Registrationdate:	23/07/2014	Fiscalpower:	
Expertise Mileage:	75430	Power Kw:	100
Bodytype:	SUV	Body color:	Black
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Back	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	2633
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options	
Radio CD	Central consol F
Windows electric F	Luggage cover
Windows electric R	Front parking sensors
Cruise Control	Rear parking sensors
Steering wheel multifunctional	
Radio multimedia	
Type of headlighting	Headlighting Halogen
Type of GPS	No GPS
Type of Lining	Lining artificial leather
Type of climate control	Autom climate control

Limited Technical Inspection			
Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK


Degree of wear				
	235/55/17/99 H LightMetal			
Winter tyres:	Fr.L.	Bridgestone: 6 mm	Fr.R.	Bridgestone: 6 mm
	Re.L.	Bridgestone: 5 mm	Re.R.	Bridgestone: 5 mm

Assistance equipment			
Repair kit	Yes	Compressor	Yes
Total cost ex VAT			1011,65
Wing F R, Bad repair, Acceptable			0,00

Bumper R, Scratch(es), LI - Repair and paint (complete)	
211,80	

Bumper R, Scratch(es), LI - Repair and paint (complete)	
211,80	

Door F R, Dent(s) and scratch(es), LI - Repair and paint (complete) 318,35



Bonnet, Bad repair, Acceptable 0,00



Roof, Chemical pollution, LI - Repair and paint (complete) 481,50



Wing R L, Bad repair, Acceptable 0,00



Front bumper, Scratch(es), Acceptable 0,00

No pictures to display

Wing R R, Bad repair, Acceptable 0,00



Door R R, Bad repair, Acceptable 0,00

