



BMW X5: 1NUE988

Vinnumber:	WBAKS410700C38453	Versionname:	
First Registrationdate:	5/02/2014	Fiscalpower:	
Expertise Mileage:	150099	Power Kw:	190
Bodytype:		Body color:	Dark Blue
Gearbox:	Automatic	Paint type:	Metalic
Transmission:	4 Weel	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OK	Parking lot:	1116
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Seats electric F L
GPS storage	HD	Seats electric F R
GPS storage		Sun Roof electric
Windows electric F		Panoramic roof
Windows electric R		Central consol F
Cruise Control		Luggage cover
Steering wheel multifunctional		Front parking sensors
Seats F heated		Rear parking sensors
Type of headlighting	Headlighting Xenon	
Type of GPS	GPS big screen color	
Type of Lining	Lining leather	
Type of climate control	Autom climate control	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	NOT OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	255/50/19/107 W LightMetal			
Summer tyres:	Fr.L.	Goodyear: 0,3 mm	Fr.R.	Goodyear: 0,3 mm
	Re.L.	N.D.	Re.R.	N.D.
	255/50/19/107 W LightMetal			
Winter tyres:	Fr.L.	N.D.	Fr.R.	N.D.
	Re.L.	Pirelli: 3 mm	Re.R.	Pirelli: 3 mm

Assistance equipment

Runflat	Yes
---------	------------

Total cost ex VAT	1774,50
Front bumper, Scratch(es), LI - Repair and paint (complete)	254,16



Backrest cover F R, Damaged, Smart repair	64,32
---	--------------



Alloy rim F L, Scratch(es), Acceptable 0,00

No pictures to display

Door frame R R, Scratch(es), Acceptable 0,00

No pictures to display

Rear window, Scratch(es), Acceptable 0,00

No pictures to display

Alloy rim R R, Scratch(es), Acceptable 0,00

No pictures to display

Bumper R, Broken, Le - Replace and paint 766,80




Tyre R R, Missing, E - Replace 153,60



Wing R R, Scratch(es), Acceptable 0,00

No pictures to display

Door F R, Dent(s) and scratch(es), LI - Repair and paint (complete) 382,02



Bonnet, Scratch(es), Acceptable 0,00

No pictures to display

Tyre R L, Missing, E - Replace 153,60



Tailgate, Scratch(es), Acceptable 0,00

No pictures to display