



OPEL Corsa: 1FNF290

Vinnnumber:	W0L0SDL68D4274164	Versionname:	CORSA BER ecoFL.Enjoy
First Registrationdate:	27/08/2013	Fiscalpower:	Active DPF 95PK
Expertise Mileage:	54966	Power Kw:	70
Bodytype:		Body color	Dark Grey
Gearbox:	MAN 5 VIT	Paint type	Metalic
Transmission:	Front	Rims summer	Aluminium
Fueltype:	Diesel	Oil level	OK
Maintenance	OK	Parking lot	4405
Battery functioning	Yes		
Number of doors	5		
Number of seats	5		
Number head rests	4		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		

Options

Radio CD		Luggage cover	
GPS storage	HD	Rear parking sensors	
GPS storage		Type of Tow bar	No Tow bar
Windows electric F			
Cruise Control			
Steering wheel multifunctional			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Manual climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	185/65/15/88 T LightMetal			
Summer tyres:	Fr.L.	Continental: 6 mm	Fr.R.	Continental: 6 mm
	Re.L.	Continental: 7 mm	Re.R.	Continental: 7 mm

Assistance equipment

Spare wheel	Yes	Jack	Yes
-------------	------------	------	------------

Total cost ex VAT	1542,36
--------------------------	----------------

Door R L, Scratch(es), LI - Repair and paint (complete)	254,68
--	---------------



Alloy rim F R, Scratch(es), LI - Repair and paint (complete)	95,00
---	--------------



Door panel R L, Scratch(es), Smart repair 110,64



Wing F R, Bad repair, Acceptable 0,00



Door F L, Scratch(es), Acceptable 0,00

No pictures to display

Rearview mirror housing R, Scratch(es), LI - Repair and paint (complete) 115,56



Door R R, Scratch(es), LI - Repair and paint (complete) 254,68



Bumper R, Scratch(es), Acceptable 0,00

No pictures to display

Bodywork, Not original part, Acceptable 0,00



Door F R, Scratch(es), LI - Repair and paint (complete) 254,68



Rearview mirror housing L, Scratch(es), LI - Repair and paint (complete) 115,56



Wing R L, Scratch(es), LI - Repair and paint (complete) 246,56



Alloy rim F L, Scratch(es), LI - Repair and paint (complete) 95,00

