



OPEL Astra: 1FNT351

Vinnnumber:	W0LPD8EW1D8076718	Versionname:	ASTRA BRE ecoFL Enjoy Active St/St 110PK
First Registrationdate:	2/09/2013	Fiscalpower:	
Expertise Mileage:	120395	Power Kw:	81
Bodytype:	Break	Body color:	Dark Brown
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	4624
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Steel		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Luggage cover	
Windows electric F		Rear parking sensors	
Windows electric R			
Cruise Control			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	215/60/16/95 V Steel			
Summer tyres:	Fr.L.	Continental: 4 mm	Fr.R.	Continental: 4 mm
	Re.L.	Continental: 5 mm	Re.R.	Continental: 5 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	522,30
-------------------	---------------

Bumper R, Scratch(es), Acceptable	0,00
-----------------------------------	-------------

No pictures to display

Door R L, Scratch(es), Acceptable	0,00
-----------------------------------	-------------

No pictures to display

Front bumper, Dent(s) and scratch(es), LI - Repair and paint (complete)	211,80
---	---------------



Tailgate, Scratch(es), Acceptable	0,00
-----------------------------------	-------------

No pictures to display

Door F R, Scratch(es), Acceptable	0,00
-----------------------------------	-------------

No pictures to display

Sill outer R, Dent(s), LI - Repair and paint (complete) 310,50



Roof, Chemical pollution, Acceptable 0,00

No pictures to display

Door R R, Scratch(es), Acceptable 0,00

No pictures to display