



OPEL Insignia: 1CNP453			
Vinnumber:	WOLGT8EL5C1049344	Versionname:	INSIGNIA BRE ecofl.Cosmo S/S DPF 130PK
First Registrationdate:	12/01/2012	Expertise Mileage:	120695
Bodytype:	Break	Fiscalpower:	96
Gearbox:	MAN 6 VIT	Power Kw:	96
Transmission:	Front	Body color:	Dark Blue
Fueltype:	Diesel	Paint type:	Metalic
Battery functioning:	Yes	Rims summer:	Aluminium
Number of doors:	5	Oil level:	OK
Number of seats:	5	Parking lot:	4610
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		

Options	
Radio CD	Central consol F
Windows electric F	Luggage cover
Windows electric R	Front parking sensors
Cruise Control	Rear parking sensors
Steering wheel multifunctional	
Radio multimedia	
Type of headlighting:	Headlighting Xenon
Type of GPS:	GPS big screen color
Type of Lining:	Lining semi-artificial leather
Type of climate control:	Autom climate control

Limited Technical Inspection			
Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear				
Summer tyres:	245/45/18/100 W LightMetal			
	Fr.L.	Michelin: 5 mm	Fr.R.	Michelin: 5 mm
	Re.L.	Michelin: 5 mm	Re.R.	Michelin: 5 mm






Assistance equipment			
Spare wheel	Yes	Jack	Yes
Total cost ex VAT	1585,23		
Alloy rim F R, Scratch(es), LI - Repair and paint (complete)	95,00		



Bumper R, Scratch(es), LI - Repair and paint (complete)	211,80
---	---------------



Door R L, Scratch(es), Acceptable	0,00
-----------------------------------	-------------

<i>No pictures to display</i>		
Door F L, Scratch(es), Acceptable		0,00
<i>No pictures to display</i>		
Front bumper, Scratch(es), LI - Repair and paint (complete)		211,80
		
Wing R R, Scratch(es), LI - Repair and paint (complete)		308,20
		
Door F R, Scratch(es), LI - Repair and paint (complete)		318,35
		
Wing R L, Bad repair, Acceptable		0,00
		
Bonnet, Chemical polution, LI - Repair and paint (complete)		290,08
		
Door R R, Scratch(es), Acceptable		0,00
<i>No pictures to display</i>		
Ignition key, Broken, E - Replace		150,00
