



**RENAULT CLIO: FA5627**

Vinnumber:	<b>VF15RJL0H51438802</b>	Versionname:	<b>1.5 ENERGY DCI 90E BUSINESS</b>
First Registrationdate:	<b>16/02/2015</b>	Fiscalpower:	
Expertise Mileage:	<b>85500</b>	Power Kw:	<b>66</b>
Bodytype:	<b>Hatchback</b>	Body color:	<b>White</b>
Gearbox:	<b>MAN 5 VIT</b>	Paint type:	<b>Opaque</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Steel</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Maintenance:	<b>OK</b>	Parking lot:	<b>3629</b>
Battery functioning:	<b>Yes</b>		
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>4</b>		
Rims summer:	<b>Steel</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

**Options**

GPS storage	<b>HD</b>	Central consol F	
GPS storage		Luggage cover	
Windows electric F		Rear parking sensors	
Cruise Control		Type of Tow bar	<b>No Tow bar</b>
Steering wheel multifunctional			
Type of headlighting	<b>Headlighting Halogen</b>		
Type of GPS	<b>GPS big screen color</b>		
Type of Lining	<b>Lining fabrics</b>		
Type of climate control	<b>Manual climate control</b>		

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

	<b>185/65/15/88 H Steel</b>			
Summer tyres:	Fr.L.	<b>Michelin: 4 mm</b>	Fr.R.	<b>Michelin: 4 mm</b>
	Re.L.	<b>Michelin: 5 mm</b>	Re.R.	<b>Michelin: 5 mm</b>

**Assistance equipment**

Spare wheel	<b>Yes</b>	Jack	<b>Yes</b>
-------------	------------	------	------------

Total cost ex VAT	<b>1085,02</b>
-------------------	----------------

Windscreen, Scratch(es), E - Replace	<b>413,76</b>
--------------------------------------	---------------



Headlight R, Missing, E - Replace	<b>6,00</b>
-----------------------------------	-------------



	<b>0,00</b>
--	-------------

Wheel cover R L, Scratch(es), Acceptable 0,00

No pictures to display

Wheel cover R R, Scratch(es), E - Replace 24,00




Interior, Dirty, Acceptable 0,00

No pictures to display


Bumper R, Chemical polution, Acceptable 0,00

No pictures to display

Bonnet, Chemical polution, LI - Repair and paint (complete) 232,06



Roof, Chemical polution, LI - Repair and paint (complete) 385,20



Tailgate, Chemical polution, Acceptable 0,00

No pictures to display

Wheel cover F R, Scratch(es), E - Replace 24,00



Bumper corner R R, Scratch(es), Acceptable 0,00

No pictures to display