



RENAULT Master 35 L3H1: 1EEX815			
Vinnnumber:	VF1MBH4J247825238	Versionname:	MASTER 35 CH2C LWB L3H1 Conf.(E5)125PK
First Registrationdate:	12/11/2012	Fiscalpower:	
Expertise Mileage:	189734	Power Kw:	92
Bodytype:	Transporter	Body color	White
Gearbox:	MAN 6 VIT	Paint type	Metalic
Transmission:		Rims summer	Aluminium
Fueltype:	Diesel	Oil level	OK
Battery functioning	Yes	Parking lot	LCV29
Number of doors	4		
Number of seats	7		
Number head rests	7		
Rims summer	Aluminium		
Category	Light Commercial Vehicle		
Oil level	OK		

Options			
Radio CD		Central consol F	
Windows electric F		Rear parking sensors	
Radio multimedia		Type of Tow bar	Tow bar fixed
Type of headlighting	Headlighting Halogen		
Type of GPS	No GPS		
Type of Lining	Lining fabrics		
Type of climate control	Manual climate control		

Limited Technical Inspection			
Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear				
Summer tyres:	225/65/16/112 R LightMetal			
	Fr.L.	Fulda: 8 mm	Fr.R.	Fulda: 8 mm
	Re.L.	Fulda: 8 mm	Re.R.	Fulda: 8 mm

Assistance equipment	
Spare wheel	Yes
Total cost ex VAT	1004,66
Tailgate, Dent(s), It - Spot repair	115,56



Bumper F R, Scratch(es), Acceptable	0,00
No pictures to display	
Rocker panel inner F L, Dent(s), LI - Repair and paint (complete)	115,56



Roof, Dent(s) and scratch(es), LI - Repair and paint (complete)	361,13
---	--------



Steering wheel, Worn, Acceptable

0,00



Door seal F L, Deformed / Strained, E - Replace

46,50



Door moulding Lower R R, Scratch(es), E - Replace

91,50



Sill outer R, Scratch(es), Acceptable

0,00

No pictures to display

Wing R L, Dent(s), Acceptable

0,00

No pictures to display

Wing R R, Dent(s), It - Spot repair

115,56



Bumper R, Deformed / Strained, LI - Repair and paint (complete)

158,85

