


**RENAULT Grand Scenic: 1HFB602**

Vinnnumber:	<b>VF1JZ14M650054061</b>	Versionname:	<b>GRAND SCENIC Energy R-Movie 5pl.110PK</b>
First Registrationdate:	<b>4/07/2014</b>	Fiscalpower:	
Expertise Mileage:	<b>134189</b>	Power Kw:	<b>81</b>
Bodytype:		Body color:	<b>Silver</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:		Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>1123</b>
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

**Options**

Radio CD	Central consol F
TV/DVD screen R	Luggage cover
Windows electric F	Front parking sensors
Windows electric R	Rear parking sensors
Cruise Control	Type of Tow bar
Steering wheel multifunctional	<b>Tow bar removable</b>
Type of headlighting	<b>Headlighting Halogen</b>
Type of GPS	<b>GPS big screen color</b>
Type of Lining	<b>Lining semi-leather</b>
Type of climate control	<b>Autom climate control</b>

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

	<b>205/55/17/95 H LightMetal</b>			
Winter tyres:	Fr.L.	<b>Pirelli: 4 mm</b>	Fr.R.	<b>Pirelli: 4 mm</b>
	Re.L.	<b>Pirelli: 5 mm</b>	Re.R.	<b>Pirelli: 5 mm</b>

**Assistance equipment**

Spare wheel	<b>Yes</b>	Jack	<b>Yes</b>
-------------	------------	------	------------

Total cost ex VAT	573,60
Door moulding Lower R R, Scratch(es), E - Replace	0,00



Alloy rim F L, Scratch(es), Acceptable	0,00
--	------

*No pictures to display*

Door moulding Lower F R, Scratch(es), E - Replace	0,00
---	------



Wing F R, Scratch(es), LI - Repair and paint (complete) 0,00



Door F R, Dent(s) and scratch(es), Le - Replace and paint 0,00



Front bumper, Scratch(es), LI - Repair and paint (complete) 211,80



Wing R R, Dent(s) and scratch(es), LI - Repair and paint (complete) 0,00



Alloy rim R R, Scratch(es), Acceptable 0,00

No pictures to display

Door R R, Dent(s) and scratch(es), Le - Replace and paint 0,00



Bumper R, Scratch(es), LI - Repair and paint (complete) 211,80



Boot carpet, Dirty, Chemical cleaning 150,00

