


PEUGEOT 2008: 1HHY075

Vinnumber:	VF3CU8HR0EY005789	Versionname:	2008 Active 68PK
First Registrationdate:	29/07/2014	Fiscalpower:	
Expertise Mileage:	117918	Power Kw:	50
Bodytype:		Body color:	Grey
Gearbox:	MAN 5 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Maintenance:	NOT OK	Parking lot:	2624
Maintenance:	-1200KM		
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Steel		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

GPS storage	HD	Luggage cover	
GPS storage		Rear parking sensors	
Windows electric F		Type of Tow bar	No Tow bar
Cruise Control			
Steering wheel multifunctional			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Manual climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

205/55/16/91 T Steel				
Winter tyres:	Fr.L.	Michelin: 3 mm	Fr.R.	Michelin: 3 mm
	Re.L.	Michelin: 6 mm	Re.R.	Michelin: 6 mm

Assistance equipment

Emergency spare wheel	Yes	Jack	Yes
-----------------------	------------	------	------------

Total cost ex VAT	1362,96
-------------------	---------

Door panel trim R L, Scratch(es), Acceptable	0,00
--	------

No pictures to display

Maintenance, Maintenance, Execute	0,00
-----------------------------------	------

No pictures to display












Bumper corner R L, Scratch(es), Acceptable	0,00
--	------

No pictures to display

Wing R R, Chemical polution, LI - Repair and paint (complete)	308,20
---	--------



Roof, Chemical polution, LI - Repair and paint (complete)	481,50
---	--------

<i>No pictures to display</i>		
		
Door F R, Dent(s), PDR - Knock out without painting		63,00
		
Wing F L, Chemical polution, LI - Repair and paint (complete)		220,18
		
Bonnet, Chemical polution, LI - Repair and paint (complete)		290,08
		
		
Wheel cover F R, Scratch(es), Acceptable		0,00
<i>No pictures to display</i>		
Bumper corner R R, Scratch(es), Acceptable		0,00
<i>No pictures to display</i>		
Tailgate, Scratch(es), Acceptable		0,00
<i>No pictures to display</i>		