



OPEL Combo Cargo: BU5655			
Vinnumber:	W0L6AXA1AD9533845	Versionname:	COMBO TOUR L1H1 Enjoy 95PK
First Registrationdate:	19/08/2013	Fiscalpower:	
Expertise Mileage:	45856	Power Kw:	70
Bodytype:	Hatchback	Body color:	Red
Gearbox:	MAN 5 VIT	Paint type:	Opaque
Transmission:	Front	Rims summer:	Steel
Fueltype:	Petrol	Oil level:	OK
Battery functioning:	Yes	Parking lot:	2525
Number of doors:	6		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Steel		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options			
Radio CD		Rear parking sensors	
Windows electric F		Type of Tow bar	Tow bar fixed
Type of headlighting	Headlighting Halogen		
Type of GPS	No GPS		
Type of Lining	Lining fabrics		
Type of climate control	Manual climate control		

Limited Technical Inspection			
Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear				
	195/60/16/97 T Steel			
Winter tyres:	Fr.L.	Uniroyal: 5 mm	Fr.R.	Uniroyal: 5 mm
	Re.L.	Uniroyal: 6 mm	Re.R.	Uniroyal: 6 mm

Assistance equipment	
Total cost ex VAT	1483,67
Front bumper, Broken, Le - Replace and paint	575,25



Aerial, Damaged, E - Replace	11,25
------------------------------	-------



Bumper grille, Broken, E - Replace	54,00
------------------------------------	-------



Door F L, Dent(s) and scratch(es), LI - Repair and paint (complete)	238,76
---	--------



Ignition key, Missing, E - Replace	150,00
------------------------------------	--------

No pictures to display

Bumper R, Scratch(es), LI - Repair and paint (complete)	158,85
---	--------



Trunk door R R, Dent(s) and scratch(es), It - Spot repair	115,56
---	--------



Bodywork, Not original part, Acceptable	0,00
---	------

No pictures to display

Luggage space cover, Missing, E - Replace	180,00
---	--------

