



VOLKSWAGEN Touran: 1DLK525

Vinnnumber:	WVGZZZ1TZDW002265	Versionname:	TOURAN Trendline BMT Start/Stop 105PK
First Registrationdate:	15/06/2012	Fiscalpower:	
Expertise Mileage:	167758	Power Kw:	77
Bodytype:		Body color:	Red
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	3631
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		

Options

Radio CD	Central consol F
Windows electric F	Luggage cover
Windows electric R	Rear parking sensors
Cruise Control	Type of Tow bar
Steering wheel multifunctional	No Tow bar
Type of headlighting	Headlighting Halogen
Type of GPS	No GPS
Type of Lining	Lining fabrics
Type of climate control	Autom climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	205/55/16/91 V LightMetal			
Summer tyres:	Fr.L.	Uniroyal: 6 mm	Fr.R.	Uniroyal: 6 mm
	Re.L.	Dunlop: 4 mm	Re.R.	Dunlop: 4 mm

Assistance equipment

Repair kit	No	Compressor	No
------------	-----------	------------	-----------

Total cost ex VAT	1340,68
-------------------	----------------

Alloy rim R R polished, Scratch(es), Acceptable	0,00
---	-------------

No pictures to display

Tyre repair kit, Missing, E - Replace	210,53
---------------------------------------	---------------



Internal Boot Lining R, Scratch(es), Acceptable	0,00
---	-------------

No pictures to display

Console storage compartment, Damaged, E - Replace	153,20
---	---------------

No pictures to display

Alloy rim F L polished, Scratch(es), Acceptable	0,00
---	-------------

No pictures to display

Internal Boot Lining L, Scratch(es), Acceptable	0,00
---	-------------

No pictures to display

Interior, Stain, Cleaning 100,00



Bumper R, Scratch(es), LI - Repair and paint (complete) 211,80



Trunk lid covering R, Scratch(es), Acceptable 0,00

No pictures to display

Bonnet, Bad repair, Acceptable 0,00



Wing R R, Dent(s), PDR - Knock out without painting 63,00



Tailgate, Dent(s), Acceptable 0,00

No pictures to display

Floor covering F L, Tear, Acceptable 0,00

No pictures to display

Sill outer L, Bad repair, Acceptable 0,00



Front bumper, Scratch(es), LI - Repair and paint (complete) 211,80



Windscreen, Stone chip(s), Acceptable 0,00

No pictures to display

Door R L, Bad repair, Acceptable 0,00



Alloy rim F R polished, Scratch(es), Acceptable 0,00

No pictures to display

Door R R, Dent(s) and scratch(es), LI - Repair and paint (complete) 390,35

