



VOLKSWAGEN Golf: 1EXN467

| | | | |
|-------------------------|--------------------------|--------------|---------------------------------|
| Vinnnumber: | WVWZZZAUZDW129157 | Versionname: | GOLF BER Trendline 105PK |
| First Registrationdate: | 15/04/2013 | Fiscalpower: | |
| Expertise Mileage: | 122998 | Power Kw: | 77 |
| Bodytype: | | Body color: | Silver |
| Gearbox: | MAN 5 VIT | Paint type: | Metalic |
| Transmission: | | Rims summer: | Steel |
| Fueltype: | Diesel | Oil level: | OK |
| Battery functioning: | Yes | Parking lot: | 3122 |
| Number of doors: | 5 | | |
| Number of seats: | 5 | | |
| Number head rests: | 5 | | |
| Rims summer: | Steel | | |
| Category: | Passenger Car | | |
| Oil level: | OK | | |

Options

| | | | |
|------------------------------|------------------------------|------------------|-------------------|
| Radio CD | | Central consol F | |
| Windows electric F | | Luggage cover | |
| Cruise Control | | Type of Tow bar | No Tow bar |
| Steering wheel multifunction | | | |
| Radio multimedia | | | |
| Type of headlighting | Headlighting Halogen | | |
| Type of GPS | GPS big screen color | | |
| Type of Lining | Lining fabrics | | |
| Type of climate control | Autom climate control | | |

Limited Technical Inspection

| | | | |
|---------------------|-----------|---------------------|------------|
| Airco functioning | OK | Battery functioning | Yes |
| Tires wear profile | OK | Power steering | Yes |
| Idle position | OK | Sound engine | OK |
| Engine startingtime | OK | Clutch test | OK |
| Exhaust gass | OK | Wiper fluid level | OK |
| Handbrake | OK | Transmission | OK |
| | | Lighting | OK |
| | | Wiperblades | OK |

Degree of wear

| | | | | |
|---------------|-----------------------------|-----------------------|-------|-----------------------|
| | 195/65/15/91 H Steel | | | |
| Summer tyres: | Fr.L. | Michelin: 5 mm | Fr.R. | Michelin: 5 mm |
| | Re.L. | Michelin: 4 mm | Re.R. | Michelin: 4 mm |

Assistance equipment

| | |
|-----------------------|------------|
| Emergency spare wheel | Yes |
|-----------------------|------------|

| | |
|---|--------|
| Total cost ex VAT | 896,18 |
| Wing R L, Dent(s) and scratch(es), LI - Repair and paint (complete) | 308,20 |



| | |
|---|-------|
| Tailgate, Scratch(es), Acceptable | 0,00 |
| <i>No pictures to display</i> | |
| Wheel cover F R, Scratch(es), E - Replace | 30,00 |



Bonnet, Dent(s), Acceptable 0,00

No pictures to display Door R R, Dent(s), PDR - Knock out without painting 63,00



Wing F R, Dent(s) and scratch(es), LI - Repair and paint (complete) 220,18



Interior, Dirty, Cleaning 0,00



Wing R R, Dent(s), PDR - Knock out without painting 63,00



Bumper R, Dent(s) and scratch(es), LI - Repair and paint (complete) 211,80

