


SKODA Octavia: 1HNU877

Vinnnumber:	TMBJG7NE2E0229865	Versionname:	OCTAVIA COMBI Ambition
First Registrationdate:	1/09/2014	Fiscalpower:	105PK
Expertise Mileage:	124486	Power Kw:	77
Bodytype:		Body color:	Grey
Gearbox:	MAN 5 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OK	Parking lot:	4505
Maintenance:	24100		
Maintenance:	316 DAGEN		
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Central consol F	
GPS storage		Luggage cover	
GPS storage	SD	Front parking sensors	
Windows electric F		Rear parking sensors	
Windows electric R		Type of Tow bar	Tow bar removable
Cruise Control			
Steering wheel multifunctional			
Seats F heated			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS base		
Type of Lining	Lining fabrics		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	205/55/16/91 V LightMetal			
Summer tyres:	Fr.L.	Continental: 6 mm	Fr.R.	Continental: 6 mm
	Re.L.	Continental: 5 mm	Re.R.	Continental: 5 mm

Assistance equipment

Spare wheel	Yes	Jack	Yes
-------------	------------	------	------------

Total cost ex VAT	634,28
-------------------	---------------

Front bumper, Dent(s) and scratch(es), LI - Repair and paint (complete)	235,80
---	---------------





Rear bulkhead lining, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Bonnet, Stone chip(s), Acceptable	0,00
<i>No pictures to display</i>	
Alloy rim F R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Wing R R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Floor covering F L, Burned, Acceptable	0,00
<i>No pictures to display</i>	
Ceiling, Stain, Cleaning	25,00



Door F R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Internal Boot Lining L, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Bumper grille, Broken, E - Replace	32,40



Tailgate, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Door panel R R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Bumper R, Dent(s) and scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Internal Boot Lining R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Door frame R L, Dent(s), Acceptable	0,00
<i>No pictures to display</i>	
Bumper grille, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Windscreen, Stone chip(s), Acceptable	0,00
<i>No pictures to display</i>	
Door R L, Dent(s) and scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Trunk lid covering R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Sill trim R R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Door F L, Dent(s) and scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Wing R L, Dent(s) and scratch(es), LI - Repair and paint (complete)	332,20



Shutter / cover, Broken, E - Replace

8,88

