


SKODA Octavia: 1GRU813

Vinnnumber:	TMBAG7NE4E0182919	Versionname:	OCTAVIA BER GreenLine Ambition 110PK
First Registrationdate:	10/04/2014	Fiscalpower:	
Expertise Mileage:	188704	Power Kw:	81
Bodytype:	Hatchback	Body color:	Silver
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	2819
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD	Central consol F
Windows electric F	Luggage cover
Windows electric R	Front parking sensors
Cruise Control	Rear parking sensors
Steering wheel multifunctional	
Seats F heated	
Radio multimedia	
Type of headlighting:	Headlighting Halogen
Type of GPS:	GPS big screen color
Type of Lining:	Lining fabrics
Type of climate control:	Autom climate control
Adaptive cruise control	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	205/55/16/92 V LightMetal			
Summer tyres:	Fr.L.	Firestone: 3 mm	Fr.R.	Firestone: 3 mm
	Re.L.	Firestone: 5 mm	Re.R.	Firestone: 5 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT 564,88

Bumper R, Scratch(es), LI - Repair and paint (complete) 211,80

Wing R R, Repaired, Acceptable 0,00

No pictures to display
Rear spoiler, Scratch(es), Acceptable 0,00

No pictures to display
Bonnet, Dent(s) and scratch(es), LI - Repair and paint (complete) 290,08



Wing F R, Scratch(es), Acceptable 0,00

No pictures to display

Wing R R, Dent(s), PDR - Knock out without painting 63,00



Door R R, Scratch(es), Acceptable 0,00

No pictures to display