



VOLKSWAGEN Golf: 1GG833

Vinnnumber:	WVWZZZAUZEP546966	Versionname:	GOLF VAR Trendline 105PK
First Registrationdate:	4/02/2014	Fiscalpower:	
Expertise Mileage:	82350	Power Kw:	77
Bodytype:		Body color:	Grey
Gearbox:	MAN 5 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OK	Parking lot:	3612
Maintenance:	SERVICE IN 21400KM 185D		
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Steel		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Central consol F	
GPS storage	SD	Luggage cover	
GPS storage		Front parking sensors	
Windows electric F		Rear parking sensors	
Windows electric R		Type of Tow bar	No Tow bar
Cruise Control			
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Autom climate control		
Adaptive cruise control			

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	195/65/15/91 H Steel			
Summer tyres:	Fr.L.	Vredestein: 6 mm	Fr.R.	Vredestein: 7 mm
	Re.L.	Vredestein: 7 mm	Re.R.	Vredestein: 7 mm

Assistance equipment

Emergency spare wheel	Yes	Jack	Yes
-----------------------	------------	------	------------

Total cost ex VAT	241,80
--------------------------	---------------

Front bumper, Scratch(es), LI - Repair and paint (complete)	211,80
--------------------------------------------------------------------	---------------





Wheel cover F R, Scratch(es), Acceptable	0,00
------------------------------------------	------

No pictures to display

Wheel cover R L, Scratch(es), E - Replace	30,00
-------------------------------------------	-------



Door F R, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Wheel cover F L, Scratch(es), Acceptable	0,00
------------------------------------------	------

No pictures to display

Bumper R, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Tailgate, Dent(s), Acceptable	0,00
-------------------------------	------

No pictures to display

Door F L, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display