


**SKODA Octavia: 1DSL427**

|                         |                          |              |                                                  |
|-------------------------|--------------------------|--------------|--------------------------------------------------|
| Vinnnumber:             | <b>TMBHT21Z7D2043036</b> | Versionname: | <b>OCTAVIA COMBI GTec<br/>Ambition DPF 105PK</b> |
| First Registrationdate: | <b>10/08/2012</b>        | Fiscalpower: |                                                  |
| Expertise Mileage:      | <b>131598</b>            | Power Kw:    | <b>77</b>                                        |
| Bodytype:               | <b>Break</b>             | Body color:  | <b>Black</b>                                     |
| Gearbox:                | <b>MAN 6 VIT</b>         | Paint type:  | <b>Metalic</b>                                   |
| Transmission:           |                          | Rims summer: | <b>Aluminium</b>                                 |
| Fueltype:               | <b>Diesel</b>            | Oil level:   | <b>OK</b>                                        |
| Battery functioning:    | <b>Yes</b>               | Parking lot: | <b>2327</b>                                      |
| Number of doors:        | <b>5</b>                 |              |                                                  |
| Number of seats:        | <b>5</b>                 |              |                                                  |
| Number head rests:      | <b>5</b>                 |              |                                                  |
| Rims summer:            | <b>Aluminium</b>         |              |                                                  |
| Category:               | <b>Passenger Car</b>     |              |                                                  |
| Oil level:              | <b>OK</b>                |              |                                                  |

**Options**

|                                |                              |                      |                          |
|--------------------------------|------------------------------|----------------------|--------------------------|
| Radio CD                       |                              | Central consol F     |                          |
| Windows electric F             |                              | Luggage cover        |                          |
| Cruise Control                 |                              | Rear parking sensors |                          |
| Steering wheel multifunctional |                              | Type of Tow bar      | <b>Tow bar removable</b> |
| Seats F heated                 |                              |                      |                          |
| Type of headlighting           | <b>Headlighting Halogen</b>  |                      |                          |
| Type of GPS                    | <b>GPS big screen color</b>  |                      |                          |
| Type of Lining                 | <b>Lining fabrics</b>        |                      |                          |
| Type of climate control        | <b>Autom climate control</b> |                      |                          |

**Limited Technical Inspection**

|                     |           |                     |               |
|---------------------|-----------|---------------------|---------------|
| Airco functioning   | <b>OK</b> | Battery functioning | <b>Yes</b>    |
| Tires wear profile  | <b>OK</b> | Power steering      | <b>Yes</b>    |
| Idle position       | <b>OK</b> | Sound engine        | <b>OK</b>     |
| Engine startingtime | <b>OK</b> | Clutch test         | <b>OK</b>     |
| Exhaust gass        | <b>OK</b> | Wiper fluid level   | <b>OK</b>     |
| Handbrake           | <b>OK</b> | Transmission        | <b>OK</b>     |
|                     |           | Lighting            | <b>NOT OK</b> |
|                     |           | Wiperblades         | <b>OK</b>     |

**Degree of wear**

|               |                                  |                          |       |                          |
|---------------|----------------------------------|--------------------------|-------|--------------------------|
|               | <b>195/65/15/91 V LightMetal</b> |                          |       |                          |
| Summer tyres: | Fr.L.                            | <b>Continental: 8 mm</b> | Fr.R. | <b>Continental: 8 mm</b> |
|               | Re.L.                            | <b>Michelin: 4 mm</b>    | Re.R. | <b>Michelin: 4 mm</b>    |

**Assistance equipment**

|             |            |      |            |
|-------------|------------|------|------------|
| Spare wheel | <b>Yes</b> | Jack | <b>Yes</b> |
|-------------|------------|------|------------|

 Total cost ex VAT 318,35

 Door F R, Dent(s) and scratch(es), LI - Repair and paint (complete) 318,35

 Wing R R, Scratch(es), Acceptable 0,00

No pictures to display

 Alloy rim R L, Scratch(es), Acceptable 0,00

No pictures to display

 Alloy rim F R, Scratch(es), Acceptable 0,00

No pictures to display

 Bumper R, Scratch(es), Acceptable 0,00

No pictures to display

 Alloy rim F L, Scratch(es), Acceptable 0,00

*No pictures to display*