



## VOLKSWAGEN Polo: 1E VU201

Vinnnumber:	<b>WVWZZZ6RZDY233362</b>	Versionname:	<b>POLO Highline DPF 75PK</b>
First Registrationdate:	<b>3/04/2013</b>	Fiscalpower:	
Expertise Mileage:	<b>120082</b>	Power Kw:	<b>55</b>
Bodytype:	<b>Hatchback</b>	Body color:	<b>Black</b>
Gearbox:	<b>MAN 5 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>1205</b>
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		

## Options

Radio CD	Central consol F
Windows electric F	Luggage cover
Windows electric R	
Radio multimedia	
Type of headlighting	<b>Headlighting Halogen</b>
Type of GPS	<b>GPS big screen color</b>
Type of Lining	<b>Lining fabrics</b>
Type of climate control	<b>Autom climate control</b>

## Limited Technical Inspection

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

## Degree of wear

	<b>215/45/16/86 H LightMetal</b>			
Summer tyres:	Fr.L.	<b>Bridgestone: 3 mm</b>	Fr.R.	<b>Bridgestone: 3 mm</b>
	Re.L.	<b>Bridgestone: 4 mm</b>	Re.R.	<b>Bridgestone: 4 mm</b>

## Assistance equipment

Spare wheel	<b>Yes</b>	Jack	<b>Yes</b>
-------------	------------	------	------------

Total cost ex VAT	1329,86
-------------------	---------

Front bumper, Scratch(es), Acceptable	0,00
---------------------------------------	------

No pictures to display

Wing F R, Scratch(es), LI - Repair and paint (complete)	176,14
---	--------



Sill outer R, Dent(s), LI - Repair and paint (complete)	248,40
---	--------



Bumper R, Scratch(es), LI - Repair and paint (complete)	169,44
---	--------



Door F R, Dent(s) and scratch(es), LI - Repair and paint (complete) 350,68



Roof, Dent(s), LI - Repair and paint (complete) 385,20

