



VOLKSWAGEN Passat: 1GDY870

Vinnnumber:	WVWZZZ3CZEE084764	Versionname:	PASSAT VAR Comfortline BMT 105PK
First Registrationdate:	13/01/2014	Fiscalpower:	
Expertise Mileage:	165745	Power Kw:	77
Bodytype:	Break	Body color:	Dark Grey
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OK	Parking lot:	3114
Maintenance	28900 KM OU 351 JOURS		
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD	Sun Roof electric
GPS storage	Central consol F
GPS storage	HD Luggage cover
Windows electric F	Front parking sensors
Windows electric R	Rear parking sensors
Cruise Control	
Steering wheel multifunctional	
Seats F heated	
Radio multimedia	
Type of headlighting:	Headlighting Halogen
Type of GPS:	GPS big screen color
Type of Lining:	Lining leather
Type of climate control:	Autom climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	215/55/16/97 W LightMetal			
Summer tyres:	Fr.L.	Michelin: 3 mm	Fr.R.	Michelin: 3 mm
	Re.L.	Dunlop: 6 mm	Re.R.	Dunlop: 6 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT 1420,77

Rearview mirror basis R, Broken, E - Replace 150,40



Alloy rim F L, Scratch(es), Acceptable 0,00

No pictures to display

Front bumper, Scratch(es), LI - Repair and paint (partial) 220,00



Sill outer R, Dent(s) and scratch(es), LI - Repair and paint (complete) 310,50



Rearview mirror housing R, Scratch(es), LI - Repair and paint (complete) 115,56



Rear spoiler, Dent(s), Acceptable 0,00

No pictures to display

Bumper R, Dent(s) and scratch(es), Acceptable 0,00

No pictures to display

Bumper grille, Broken, E - Replace 32,40



Wing R L, Dent(s), PDR - Knock out without painting 63,00



Alloy rim F R, Scratch(es), LI - Repair and paint (complete) 95,00



Door F L, Scratch(es), It - Spot repair 115,56




Door F R, Dent(s) and scratch(es), LI - Repair and paint (complete) 318,35



Door F R, Dent(s) and scratch(es), LI - Repair and paint (complete) 318,35





Door R L, Scratch(es), Acceptable

0,00

No pictures to display