



RENAULT Scenic: 1EXR558

Vinnumber:	VF1JZ14K648992646	Versionname:	SCENIC Expression 110PK
First Registrationdate:	16/04/2013	Fiscalpower:	
Expertise Mileage:	108540	Power Kw:	81
Bodytype:		Body color:	Grey
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OK	Parking lot:	3714
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Steel		
Category:	Passenger Car		
Oil level:	OK		

Options

Radio CD		Luggage cover	
GPS storage		Type of Tow bar	No Tow bar
GPS storage	SD		
Windows electric F			
Windows electric R			
Cruise Control			
Steering wheel multifunction			
Alarm			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Manual climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	205/60/16/92 V Steel			
Summer tyres:	Fr.L.	Other: 5 mm	Fr.R.	Other: 5 mm
	Re.L.	Michelin: 5 mm	Re.R.	Michelin: 5 mm

Assistance equipment

Spare wheel	Yes	Jack	Yes
-------------	------------	------	------------

Total cost ex VAT	1070,00
-------------------	----------------

Ignition key, Missing, E - Replace	150,00
------------------------------------	---------------

No pictures to display

Door frame R R, Scratch(es), Acceptable	0,00
---	-------------

No pictures to display

Front bumper, Scratch(es), LI - Repair and paint (complete)	211,80
---	---------------





Seat cover R R, Stain, Acceptable 0,00

No pictures to display

Door frame F L, Dent(s), Acceptable 0,00

No pictures to display

Wheel cover F R, Scratch(es), E - Replace 30,00



Bumper R, Not original part, Acceptable 0,00





Front bumper, Repaired, Acceptable 0,00



Radio, Scratch(es), Acceptable 0,00



Rear window, Scratch(es), E - Replace 370,00



Bumper R, Scratch(es), Acceptable 0,00

No pictures to display

Wing R L, Scratch(es), LI - Repair and paint (complete) 308,20

