



TOYOTA Auris: 1HFB041

Vinnnumber:	SB1ZS3JE10E073026	Versionname:	AURIS TOUR.SP. HSD Comfort CVT 99PK Aut.
First Registrationdate:	4/07/2014	Fiscalpower:	
Expertise Mileage:	94095	Power Kw:	73
Bodytype:		Body color:	Grey
Gearbox:	Automatic	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Hybrid Petrol	Oil level:	OK
Maintenance:	PCONTROLLER	Parking lot:	2426
Maintenance:	OK		
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD	Central consol F
GPS storage	Luggage cover
GPS storage	HD
Windows electric F	
Windows electric R	
Cruise Control	
Steering wheel multifunctional	
Radio multimedia	
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining fabrics
Type of climate control	Autom climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	195/65/15/91 H LightMetal			
Summer tyres:	Fr.L.	Continental: 6 mm	Fr.R.	Continental: 6 mm
	Re.L.	Continental: 6 mm	Re.R.	Continental: 6 mm

Assistance equipment


Repair kit	Yes	Compressor	Yes
		Jack	Yes

Total cost ex VAT	294,12
-------------------	---------------

Door R L, Dent(s), Acceptable	0,00
-------------------------------	-------------

<i>No pictures to display</i>	
-------------------------------	--

Bumper R, Dent(s), It - Spot repair	115,56
-------------------------------------	---------------



Wing F L, Dent(s), PDR - Knock out without painting	63,00
-----------------------------------------------------	--------------



Tailgate, Scratch(es), Acceptable 0,00

No pictures to display

Centre console, Broken, Acceptable 0,00




Front bumper, Bad repair, Acceptable 0,00



Bonnet, Bad repair, Acceptable 0,00



Spoiler R, Dent(s) and scratch(es), It - Spot repair 115,56



Door R R, Dent(s), Acceptable 0,00

No pictures to display

Wing F R, Dent(s), Acceptable 0,00

No pictures to display