



## VOLVO V40: 1FAM124

|                         |                          |              |                          |
|-------------------------|--------------------------|--------------|--------------------------|
| Vinnnumber:             | <b>YV1MV8481D2058905</b> | Versionname: | <b>V40 D2 Base 115PK</b> |
| First Registrationdate: | <b>7/05/2013</b>         | Fiscalpower: |                          |
| Expertise Mileage:      | <b>155217</b>            | Power Kw:    | <b>84</b>                |
| Bodytype:               | <b>Break</b>             | Body color:  | <b>White</b>             |
| Gearbox:                | <b>MAN 6 VIT</b>         | Paint type:  | <b>Metalic</b>           |
| Transmission:           | <b>Front</b>             | Rims summer: | <b>Aluminium</b>         |
| Fueltype:               | <b>Diesel</b>            | Oil level:   | <b>OK</b>                |
| Battery functioning:    | <b>Yes</b>               | Parking lot: | <b>3425</b>              |
| Number of doors:        | <b>5</b>                 |              |                          |
| Number of seats:        | <b>5</b>                 |              |                          |
| Number head rests:      | <b>5</b>                 |              |                          |
| Rims summer:            | <b>Aluminium</b>         |              |                          |
| Category:               | <b>Passenger Car</b>     |              |                          |
| Oil level:              | <b>OK</b>                |              |                          |

## Options

|                                |                              |                   |
|--------------------------------|------------------------------|-------------------|
| Radio CD                       | Central consol F             |                   |
| Windows electric F             | Luggage cover                |                   |
| Windows electric R             | Type of Tow bar              | <b>No Tow bar</b> |
| Cruise Control                 |                              |                   |
| Steering wheel multifunctional |                              |                   |
| Radio multimedia               |                              |                   |
| Type of headlighting           | <b>Headlighting Halogen</b>  |                   |
| Type of GPS                    | <b>GPS big screen color</b>  |                   |
| Type of Lining                 | <b>Lining fabrics</b>        |                   |
| Type of climate control        | <b>Autom climate control</b> |                   |

## Limited Technical Inspection

|                     |           |                     |            |
|---------------------|-----------|---------------------|------------|
| Airco functioning   | <b>OK</b> | Battery functioning | <b>Yes</b> |
| Tires wear profile  | <b>OK</b> | Power steering      | <b>Yes</b> |
| Idle position       | <b>OK</b> | Sound engine        | <b>OK</b>  |
| Engine startingtime | <b>OK</b> | Clutch test         | <b>OK</b>  |
| Exhaust gass        | <b>OK</b> | Wiper fluid level   | <b>OK</b>  |
| Handbrake           | <b>OK</b> | Transmission        | <b>OK</b>  |
|                     |           | Lighting            | <b>OK</b>  |
|                     |           | Wiperblades         | <b>OK</b>  |

## Degree of wear

|               |                                  |                     |       |                     |
|---------------|----------------------------------|---------------------|-------|---------------------|
|               | <b>206/55/16/91 V LightMetal</b> |                     |       |                     |
| Summer tyres: | Fr.L.                            | <b>Kleber: 4 mm</b> | Fr.R. | <b>Kleber: 4 mm</b> |
|               | Re.L.                            | <b>Kleber: 6 mm</b> | Re.R. | <b>Kleber: 6 mm</b> |

## Assistance equipment

|   |            |            |               |
|---|------------|------------|---------------|
| Repair kit                              | <b>Yes</b> | Compressor | <b>Yes</b>    |
| Total cost ex VAT                       |            |            | <b>150,00</b> |
| Ignition key, Missing, E - Replace      |            |            | <b>150,00</b> |
| <i>No pictures to display</i>           |            |            |               |
| Bumper R, Scratch(es), Acceptable       |            |            | <b>0,00</b>   |
| <i>No pictures to display</i>           |            |            |               |
| Bodywork, Not original part, Acceptable |            |            | <b>0,00</b>   |
| <i>No pictures to display</i>           |            |            |               |
| Door R L, Scratch(es), Acceptable       |            |            | <b>0,00</b>   |
| <i>No pictures to display</i>           |            |            |               |
| Alloy rim F R, Scratch(es), Acceptable  |            |            | <b>0,00</b>   |
| <i>No pictures to display</i>           |            |            |               |
| Wing R R, Dent(s), Acceptable           |            |            | <b>0,00</b>   |
| <i>No pictures to display</i>           |            |            |               |

*No pictures to display*