



VOLVO V60: 1FLC515

Vinnnumber:	YV1FW8481E1162065	Versionname:	V60 BRE D2 Kinetic 115PK
First Registrationdate:	2/08/2013	Fiscalpower:	
Expertise Mileage:	112105	Power Kw:	84
Bodytype:	Break	Body color:	Blue
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OK	Parking lot:	2821
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		

Options

Radio CD		Central consol F	
GPS storage	HD	Luggage cover	
GPS storage		Rear parking sensors	
Windows electric F		Type of Tow bar	Tow bar fixed
Windows electric R			
Cruise Control			
Steering wheel multifunctional			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	205/60/16/96 H LightMetal			
Summer tyres:	Fr.L.	Michelin: 4 mm	Fr.R.	Michelin: 4 mm
	Re.L.	Michelin: 4 mm	Re.R.	Michelin: 4 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	569,28
-------------------	--------









Door panel F L, Tear, Smart repair	110,64
------------------------------------	--------



Door panel R L, Tear, Smart repair	110,64
------------------------------------	--------



Door F L, Scratch(es), Acceptable	0,00
-----------------------------------	------

<i>No pictures to display</i>		
Alloy rim F L, Scratch(es), LI - Repair and paint (complete)		95,00
		
Door R R, Scratch(es), Acceptable		0,00
<i>No pictures to display</i>		
Alloy rim R R, Scratch(es), LI - Repair and paint (complete)		95,00
		
Internal Boot Lining L, Scratch(es), Acceptable		0,00
<i>No pictures to display</i>		
Bumper R, Scratch(es), Acceptable		0,00
<i>No pictures to display</i>		
Wing R R, Dent(s), PDR - Knock out without painting		63,00
		
Alloy rim R L, Scratch(es), Acceptable		0,00
<i>No pictures to display</i>		
Internal Boot Lining R, Scratch(es), Acceptable		0,00
<i>No pictures to display</i>		
Alloy rim F R, Scratch(es), LI - Repair and paint (complete)		95,00
		
Steering wheel, Scratch(es), Acceptable		0,00
