



AUDI Q5: 1FLQ780			
Vinnnumber:	WAUZZZ8R4EA025969	Versionname:	Q5 150PK
First Registrationdate:	8/08/2013	Fiscalpower:	
Expertise Mileage:	130153	Power Kw:	110
Bodytype:	SUV	Body color:	Anthracite
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	3225
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		

Options			
Radio CD		Sun Roof electric	
Windows electric F		Panoramic roof	
Windows electric R		Central consol F	
Cruise Control		Luggage cover	
Steering wheel multifunctional		Rear parking sensors	
Seats F heated		Type of Tow bar	Tow bar fixed
Radio multimedia			
Type of headlighting	Headlighting Xenon		
Type of GPS	GPS big screen color		
Type of Lining	Lining leather		
Type of climate control	Autom climate control		

Limited Technical Inspection			
Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear				
	235/65/17/104 V LightMetal			
Summer tyres:	Fr.L.	Goodyear: 6 mm	Fr.R.	Goodyear: 6 mm
	Re.L.	Goodyear: 6 mm	Re.R.	Goodyear: 6 mm

Assistance equipment			
Emergency spare wheel	Yes	Jack	Yes
Total cost ex VAT			683,04
Bumper R, Scratch(es), Smart repair			110,64



Front bumper, Scratch(es), LI - Repair and paint (complete)	254,16
---	--------



Bumper grille F R, Broken, E - Replace 34,08



Rear window, Scratch(es), E - Replace 0,00



Bumper R, Dent(s) and scratch(es), LI - Repair and paint (complete) 284,16



Bumper grille, Deformed / Strained, Acceptable 0,00

