



BMW 3: 1HPS278			
Vinnumber:	WBA3K11030F835273	Versionname:	3 TOURING 318d 136PK
First Registrationdate:	8/09/2014	Fiscalpower:	
Expertise Mileage:	124211	Power Kw:	100
Bodytype:	Break	Body color:	Dark Grey
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Back	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	3401
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options			
Radio CD		Sun Roof electric	
Windows electric F		Panoramic roof	
Windows electric R		Central consol F	
Steering wheel multifunctional		Luggage cover	
Radio multimedia		Rear parking sensors	
Type of headlighting	Headlighting Halogen	Type of Tow bar	Tow bar fixed
Type of GPS	GPS big screen color		
Type of Lining	Lining leather		
Type of climate control	Autom climate control		

Limited Technical Inspection			
Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear				
	225/50/17/94 H LightMetal			
Winter tyres:	Fr.L.	Dunlop: 4 mm	Fr.R.	Dunlop: 4 mm
	Re.L.	Dunlop: 5 mm	Re.R.	Dunlop: 5 mm

Assistance equipment	
	Runflat Yes

Total cost ex VAT	252,32
Protection plate M, Strained , E - Replace	74,00



Door F R, Bad repair, Acceptable	0,00
---	-------------



Door panel F L, Hole, E - Replace	114,00
--	---------------



Tailgate, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Wing F R, Bad repair, Acceptable	0,00
----------------------------------	------



Bumper R, Bad repair, Acceptable	0,00
----------------------------------	------



Front bumper, Bad repair, Acceptable	0,00
--------------------------------------	------



Backrest cover F L, Scratch(es), Smart repair	64,32
---	-------



Wing R L, Bad repair, Acceptable	0,00
----------------------------------	------



Wing R R, Bad repair, Acceptable	0,00
----------------------------------	------

