



AUDI Q3: 1HHY827			
Vinnnumber:	<b>WAUZZZ8U9ER112269</b>	Versionname:	<b>Q3 136PK</b>
First Registrationdate:	<b>29/07/2014</b>	Fiscalpower:	
Expertise Mileage:	<b>102245</b>	Power Kw:	<b>100</b>
Bodytype:	<b>SUV</b>	Body color:	<b>.</b>
Gearbox:	<b>MAN 6 VIT</b>	Body color:	<b>Blue</b>
Transmission:	<b>Front</b>	Paint type:	<b>Metalic</b>
Fueltype:	<b>Diesel</b>	Rims summer:	<b>Aluminium</b>
Battery functioning:	<b>Yes</b>	Oil level:	<b>OK</b>
Number of doors:	<b>5</b>	Parking lot:	<b>2812</b>
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

Options	
Radio CD	Central consol F
GPS storage	Luggage cover
GPS storage	SD
Windows electric F	Front parking sensors
Windows electric R	Rear parking sensors
Cruise Control	
Steering wheel multifunctional	
Type of headlighting	<b>Headlighting Halogen</b>
Type of GPS	<b>GPS big screen color</b>
Type of Lining	<b>Lining fabrics</b>
Type of climate control	<b>Autom climate control</b>
Level control	

Limited Technical Inspection			
Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

Degree of wear				
	<b>235/55/17/99 V LightMetal</b>			
Summer tyres:	Fr.L.	<b>Bridgestone: 4 mm</b>	Fr.R.	<b>Bridgestone: 4 mm</b>
	Re.L.	<b>Bridgestone: 5 mm</b>	Re.R.	<b>Bridgestone: 5 mm</b>

Assistance equipment			
Emergency spare wheel	<b>Yes</b>	Jack	<b>Yes</b>
Number of charging cables (normal)	<b>0</b>		
Number of charging cables (rapid charge)	<b>0</b>		

Total cost ex VAT	<b>725,15</b>
Tailgate, Scratch(es), Acceptable	<b>0,00</b>



Bumper R, Scratch(es), LI - Repair and paint (complete)	<b>211,80</b>
---	---------------



Door R R, Dent(s) and scratch(es), LI - Repair and paint (complete) 366,35



Wing trim R R, Scratch(es), E - Replace 84,00



Wing R R, Dent(s), PDR - Knock out without painting 63,00

