



**BMW 3 BERLINE: 1NGN384**

Vinnumber:	<b>WBA3D11010J622197</b>	Versionname:	<b>2.0 318D (100KW) BERLINE</b>
First Registrationdate:	<b>11/03/2013</b>	Fiscalpower:	
Expertise Mileage:	<b>171505</b>	Power Kw:	<b>100</b>
Bodytype:		Body color:	<b>Blue</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Back</b>	Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Maintenance:	<b>OK</b>	Parking lot:	<b>3702</b>
Battery functioning:	<b>Yes</b>		
Number of doors:	<b>4</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

**Options**

Radio CD		Central consol F	
GPS storage	<b>HD</b>	Rear parking sensors	
GPS storage		Type of Tow bar	<b>No Tow bar</b>
Windows electric F			
Windows electric R			
Cruise Control			
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	<b>Headlighting Halogen</b>		
Type of GPS	<b>GPS big screen color</b>		
Type of Lining	<b>Lining fabrics</b>		
Type of climate control	<b>Autom climate control</b>		

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

	<b>225/50/17/94 V LightMetal</b>			
Summer tyres:	Fr.L.	<b>Uniroyal: 7 mm</b>	Fr.R.	<b>Uniroyal: 7 mm</b>
	Re.L.	<b>Uniroyal: 7 mm</b>	Re.R.	<b>Uniroyal: 7 mm</b>

**Assistance equipment**

	Runflat	<b>Yes</b>
Total cost ex VAT		<b>1066,23</b>
Bumper R, Scratch(es), Acceptable		<b>0,00</b>
<i>No pictures to display</i>		
Tailgate, Scratch(es), 67 - Polish		<b>0,00</b>
<i>No pictures to display</i>		
Door R R, Dent(s) and scratch(es), Acceptable		<b>0,00</b>
<i>No pictures to display</i>		
Door R L, Dent(s), PDR - Knock out without painting		<b>63,00</b>



Front bumper, Dent(s) and scratch(es), LI - Repair and paint (complete) 211,80



Bonnet, Dent(s) and scratch(es), LI - Repair and paint (complete) 338,08



Steering wheel, Scratch(es), Acceptable 0,00

No pictures to display

Wing F R, Scratch(es), Acceptable 0,00

No pictures to display

Alloy rim F L, Scratch(es), Acceptable 0,00

No pictures to display

Wing R L, Dent(s), PDR - Knock out without painting 63,00



Door F R, Dent(s) and scratch(es), LI - Repair and paint (complete) 390,35



Door F L, Repaired, Acceptable 0,00

No pictures to display