



AUDI A6: 1FBT902

Vinnumber:	WAUZZZ4G1DN151184	Versionname:	A6 BER 136PK
First Registrationdate:	17/05/2013	Fiscalpower:	
Expertise Mileage:	173034	Power Kw:	100
Bodytype:		Body color:	Grey
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	-46 DAGEN	Parking lot:	2424
Maintenance:	NOT OK		
Battery functioning:	Yes		
Number of doors:	4		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		

Options

Radio CD		Central consol F	
GPS storage	HD	Front parking sensors	
GPS storage		Rear parking sensors	
Windows electric F		Type of Tow bar	No Tow bar
Windows electric R			
Cruise Control			
Steering wheel multifunctional			
Seats F heated			
Radio multimedia			
Type of headlighting	Headlighting LED		
Type of GPS	GPS big screen color		
Type of Lining	Lining leather		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	225/60/16/98 V LightMetal			
Summer tyres:	Fr.L.	Continental: 2 mm	Fr.R.	Continental: 2 mm
	Re.L.	Continental: 6 mm	Re.R.	Continental: 6 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	1221,76
-------------------	----------------

Wing R L, Dent(s), Acceptable	0,00
-------------------------------	-------------

No pictures to display

Ignition key, Missing, E - Replace	0,00
------------------------------------	-------------



Bonnet, Stone chip(s), Acceptable	0,00
-----------------------------------	-------------

No pictures to display

Bumper cover R M, Scratch(es), E - Replace	80,80
--	--------------



Roof, Rust, Acceptable	0,00
<i>No pictures to display</i>	
Alloy rim F R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Wing R R, Dent(s) and scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Tailgate, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Alloy rim R R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Bumper R, Dent(s) and scratch(es), LI - Repair and paint (complete)	278,16



Front bumper, Dent(s) and scratch(es), Le - Replace and paint	862,80
---	--------



Wing F R, Dent(s), Acceptable	0,00
<i>No pictures to display</i>	
Maintenance, Maintenance, Execute	0,00



Wing F L, Dent(s), Acceptable	0,00
-------------------------------	------

No pictures to display

Alloy rim R L, Scratch(es), Acceptable	0,00
--	------

No pictures to display

Windscreen, Bad repair, E - Replace	0,00
-------------------------------------	------



Alloy rim F L, Scratch(es), Acceptable	0,00
--	------

No pictures to display

Rear bulkhead lining, Scratch(es), Acceptable	0,00
---	------

No pictures to display

Door F R, Dent(s) and scratch(es), Acceptable	0,00
---	------

No pictures to display