



**OPEL MOVANO: PF8827**

Vinnnumber:	<b>WOLMRF4YEFB081732</b>	Versionname:	<b>2.3CDTI 100KW ECOFLEX S/S LWB HRF 3.5T</b>
First Registrationdate:	<b>9/07/2015</b>	Fiscalpower:	
Expertise Mileage:	<b>86383</b>	Power Kw:	<b>100</b>
Bodytype:	<b>Transporter</b>	Body color:	<b>White</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:		Rims summer:	<b>Steel</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>LCV13</b>
Number of doors:	<b>5</b>		
Number of seats:	<b>3</b>		
Number head rests:	<b>3</b>		
Rims summer:	<b>Steel</b>		
Category:	<b>Light Commercial Vehicle</b>		
Oil level:	<b>OK</b>		

**Options**

Radio CD	Central consol F	
Windows electric F	Rear parking sensors	
Cruise Control	Type of Tow bar	<b>Tow bar fixed</b>
Steering wheel multifunctional		
Radio multimedia		
Type of headlighting:	<b>Headlighting Halogen</b>	
Type of GPS:	<b>GPS big screen color</b>	
Type of Lining:	<b>Lining fabrics</b>	
Type of climate control:	<b>Manual climate control</b>	

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

	<b>225/65/16/112 R Steel</b>			
Summer tyres:	Fr.L.	<b>Michelin: 6 mm</b>	Fr.R.	<b>Michelin: 6 mm</b>
	Re.L.	<b>Michelin: 6 mm</b>	Re.R.	<b>Michelin: 6 mm</b>

**Assistance equipment**

Spare wheel	<b>Yes</b>
-------------	------------

Total cost ex VAT	1295,03
-------------------	---------


Trunk door R L, Dent(s) and scratch(es), It - Spot repair	115,56
---	--------



Door R R, Deformed / Strained, Le - Replace and paint	746,18
---	--------



Wing trim R R, Scratch(es), E - Replace	69,00
---	-------



Bumper F L, Scratch(es), Smart repair 110,64



Wheel cover F R, Missing, E - Replace 22,50



Wing R L, Dent(s) and scratch(es), LI - Repair and paint (complete) 231,15



Interior, Dirty, Cleaning 0,00

