


BMW X4: LK5809

| | | | |
|-------------------------|--------------------------|--------------|------------------------------|
| Vinnumber: | WBAXX110800R39540 | Versionname: | 2.0 XDRIVE20D (140KW) |
| First Registrationdate: | 23/11/2015 | Fiscalpower: | 4WD |
| Expertise Mileage: | 179067 | Power Kw: | 140 |
| Bodytype: | SUV | Body color: | Black |
| Gearbox: | Automatic | Paint type: | Metalic |
| Transmission: | | Rims summer: | Aluminium |
| Fueltype: | Diesel | Oil level: | OK |
| Battery functioning: | Yes | Parking lot: | 4233 |
| Number of doors: | 5 | | |
| Number of seats: | 5 | | |
| Number head rests: | 4 | | |
| Rims summer: | Aluminium | | |
| Category: | Passenger Car | | |
| Oil level: | OK | | |

Options

| | |
|--------------------------------|------------------------------|
| Radio CD | Central consol F |
| Windows electric F | Front parking sensors |
| Windows electric R | Rear parking sensors |
| Cruise Control | |
| Steering wheel multifunctional | |
| Seats F heated | |
| Radio multimedia | |
| Type of headlighting | Headlighting Xenon |
| Type of GPS | GPS big screen color |
| Type of Lining | Lining leather |
| Type of climate control | Autom climate control |

Limited Technical Inspection

| | | | |
|---------------------|-----------|---------------------|------------|
| Airco functioning | OK | Battery functioning | Yes |
| Tires wear profile | OK | Power steering | Yes |
| Idle position | OK | Sound engine | OK |
| Engine startingtime | OK | Clutch test | OK |
| Exhaust gass | OK | Wiper fluid level | OK |
| Handbrake | OK | Transmission | OK |
| | | Lighting | OK |
| | | Wiperblades | OK |

Degree of wear

| | | | | |
|---------------|----------------------------------|----------------------|-------|----------------------|
| | 225/60/17/99 H LightMetal | | | |
| Summer tyres: | Fr.L. | Pirelli: 3 mm | Fr.R. | Pirelli: 3 mm |
| | Re.L. | Pirelli: 4 mm | Re.R. | Pirelli: 4 mm |

Assistance equipment

| | | | |
|----------------------------------|------------|------------|------------|
| Repair kit | Yes | Compressor | Yes |
| Total cost ex VAT | | | 900,04 |
| Foglight R, Damaged, E - Replace | | | 156,00 |



| | |
|---|--------|
| Door F R, Scratch(es), Acceptable | 0,00 |
| <i>No pictures to display</i> | |
| Wing F L, Scratch(es), Acceptable | 0,00 |
| <i>No pictures to display</i> | |
| Tailgate, Dent(s) and scratch(es), LI - Repair and paint (complete) | 362,02 |



Door R R, Dent(s) and scratch(es), LI - Repair and paint (complete) 382,02



Door R L, Scratch(es), Acceptable 0,00

No pictures to display