



**OPEL Astra: 1FKZ215**

Vinnnumber:	<b>W0LPC6DA7D1130576</b>	Versionname:	<b>ASTRA BER ecoFLEX Essentia S&amp;S 95PK</b>
First Registrationdate:	<b>1/08/2013</b>	Fiscalpower:	
Expertise Mileage:	<b>70843</b>	Power Kw:	<b>70</b>
Bodytype:		Body color	<b>Black</b>
Gearbox:	<b>MAN 5 VIT</b>	Paint type	<b>Metalic</b>
Transmission:		Rims summer	<b>Steel</b>
Fueltype:	<b>Diesel</b>	Oil level	<b>OK</b>
Battery functioning	<b>Yes</b>	Parking lot	<b>3424</b>
Number of doors	<b>5</b>		
Number of seats	<b>5</b>		
Number head rests	<b>5</b>		
Rims summer	<b>Steel</b>		
Category	<b>Passenger Car</b>		
Oil level	<b>OK</b>		

**Options**

Radio CD		Luggage cover	
Windows electric F		Type of Tow bar	<b>No Tow bar</b>
Type of headlighting	<b>Headlighting Halogen</b>		
Type of GPS	<b>No GPS</b>		
Type of Lining	<b>Lining fabrics</b>		
Type of climate control	<b>Manual climate control</b>		

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

	<b>215/60/16/95 V Steel</b>			
Summer tyres:	Fr.L.	<b>Continental: 4 mm</b>	Fr.R.	<b>Continental: 4 mm</b>
	Re.L.	<b>Continental: 7 mm</b>	Re.R.	<b>Continental: 7 mm</b>

**Assistance equipment**


Emergency spare wheel	<b>Yes</b>	Jack	<b>Yes</b>
-----------------------	------------	------	------------


<b>Total cost ex VAT</b>	<b>1243,99</b>
--------------------------	----------------

<b>Tailgate, Dent(s), Acceptable</b>	<b>0,00</b>
--------------------------------------	-------------

*No pictures to display*

<b>Rear window, Scratch(es), E - Replace</b>	<b>0,00</b>
--	-------------






Bonnet, Chemical pollution, LI - Repair and paint (complete) 290,08



Door R R, Scratch(es), LI - Repair and paint (complete) 318,35



Rearview mirror housing R, Scratch(es), LI - Repair and paint (complete) 115,56



Bumper R, Scratch(es), Acceptable 0,00

No pictures to display

Wing R R, Scratch(es), LI - Repair and paint (complete) 308,20



Door F R, Scratch(es), Acceptable 0,00

No pictures to display

Front bumper, Scratch(es), LI - Repair and paint (complete) 211,80

