



OPEL Combo Cargo: 1ELI987			
Vinnnumber:	W0L6ZXC1AC9524162	Versionname:	COMBO 2000 B/F SWB St/St(EU5)90PK
First Registrationdate:	14/01/2013	Fiscalpower:	
Expertise Mileage:	152447	Power Kw:	66
Bodytype:	Transporter	Body color:	White
Gearbox:	MAN 5 VIT	Paint type:	Metalic
Transmission:		Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	2616
Number of doors:	4		
Number of seats:	2		
Number head rests:	2		
Rims summer:	Steel		
Category:	Light Commercial Vehicle		
Oil level:	OK		

Options			
Radio CD	Type of Tow bar	No Tow bar	
Windows electric F			
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	No GPS		
Type of Lining	Lining fabrics		
Type of climate control	Manual climate control		

Limited Technical Inspection			
Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear				
	185/65/15/88 T Steel			
Summer tyres:	Fr.L.	Uniroyal: 7 mm	Fr.R.	Uniroyal: 7 mm
	Re.L.	Pirelli: 6 mm	Re.R.	Pirelli: 6 mm

Assistance equipment	
Total cost ex VAT	494,71
Trunk door R L, Dent(s), It - Spot repair	115,56



Wing R L, Dent(s) and scratch(es), LI - Repair and paint (complete)	231,15
---	--------





Bumper R, Scratch(es), Acceptable 0,00

No pictures to display

Rearview mirror housing L, Crack, E - Replace 74,00



Rearview mirror housing R, Broken, E - Replace 74,00

