



CITROEN C4 Picasso: 1HNC721

Vinnnumber:	VF73A9HC8EJ701922	Versionname:	GR.C4 PICASSO Exclusive
First Registrationdate:	26/08/2014	Fiscalpower:	115PK
Expertise Mileage:	81976	Power Kw:	85
Bodytype:	Hatchback	Body color:	Blue
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	2804
Number of doors:	5		
Number of seats:	7		
Number head rests:	7		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD	Luggage cover
Windows electric F	Front parking sensors
Windows electric R	Rear parking sensors
Cruise Control	Type of Tow bar
Steering wheel multifunctional	Tow bar fixed
Radio multimedia	
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining semi-artificial leather
Type of climate control	Autom climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	205/55/17/95 V LightMetal			
Summer tyres:	Fr.L.	Michelin: 4 mm	Fr.R.	Michelin: 4 mm
	Re.L.	Michelin: 5 mm	Re.R.	Michelin: 5 mm

Assistance equipment

Emergency spare wheel	Yes	Jack	Yes
-----------------------	------------	------	------------

Total cost ex VAT	295,00
Alloy rim R L polished, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Bonnet, Chemical polution, Acceptable	0,00
<i>No pictures to display</i>	
Protection plate M, Deformed / Strained, E - Replace	74,00



Door F L, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Tailgate, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	

no pictures to display

Door R R, Dent(s), PDR - Knock out without painting 63,00



Trunk lid covering R, Scratch(es), Acceptable 0,00

No pictures to display

Wing R R, Dent(s), PDR - Knock out without painting 63,00



Alloy rim R R, Scratch(es), LI - Repair and paint (complete) 95,00

