



BMW 5: 1GKT020

Vinnnumber:	WBA5J110X0D065547	Versionname:	5 TOURING 518dA 136PK Aut.
First Registrationdate:	5/03/2014	Fiscalpower:	
Expertise Mileage:	68291	Power Kw:	100
Bodytype:	Break	Body color:	Grey
Gearbox:	Automatic	Paint type:	Metalic
Transmission:		Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	SHOWROOM
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD	Central consol F	
Windows electric F	Luggage cover	
Windows electric R	Front parking sensors	
Cruise Control	Rear parking sensors	
Steering wheel multifunctional	Type of Tow bar	No Tow bar
Seats F heated		
Radio multimedia		
Type of headlighting:	Headlighting Halogen	
Type of GPS:	GPS big screen color	
Type of Lining:	Lining leather	
Type of climate control:	Autom climate control	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	245/45/18/96 V LightMetal			
Winter tyres:	Fr.L.	Bridgestone: 7 mm	Fr.R.	Bridgestone: 7 mm
	Re.L.	Bridgestone: 4 mm	Re.R.	Bridgestone: 4 mm

Assistance equipment

Runflat	Yes
---------	------------

Total cost ex VAT	0,00
-------------------	-------------

Bumper R, Bad repair, Acceptable	0,00
----------------------------------	-------------



Alloy rim F L, Scratch(es), Acceptable	0,00
--	-------------

No pictures to display