



PEUGEOT 308: 1HEJ586

Vinnnumber:	VF3LCBHXHES155123	Versionname:	308 SW BlueHDi Allure STT
First Registrationdate:	1/07/2014	Fiscalpower:	116PK
Expertise Mileage:	126937	Power Kw:	85
Bodytype:	Break	Body color:	White
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:		Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	2613
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD	Central consol F
Windows electric F	Luggage cover
Windows electric R	Front parking sensors
Cruise Control	Rear parking sensors
Steering wheel multifunctional	Type of Tow bar
Radio multimedia	No Tow bar
Type of headlighting	Headlighting LED
Type of GPS	GPS big screen color
Type of Lining	Lining fabrics
Type of climate control	Autom climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	205/55/16/91 V LightMetal			
Summer tyres:	Fr.L.	Continental: 4 mm	Fr.R.	Continental: 4 mm
	Re.L.	Continental: 6 mm	Re.R.	Continental: 6 mm

Assistance equipment

Emergency spare wheel	Yes	Jack	Yes
-----------------------	------------	------	------------

Total cost ex VAT

	1645,65
Bumper R, Scratch(es), LI - Repair and paint (complete)	211,80







Front bumper, Scratch(es), LI - Repair and paint (complete) 211,80



Sill outer R, Dent(s) and scratch(es), LI - Repair and paint (complete) 310,50



Bodywork, Not original part, Acceptable 0,00

No pictures to display

Alloy rim F L polished, Scratch(es), LI - Repair and paint (complete) 95,00



Door R R, Dent(s) and scratch(es), LI - Repair and paint (complete) 318,35



Alloy rim F R polished, Scratch(es), LI - Repair and paint (complete) 95,00




Alloy rim R R polished, Scratch(es), LI - Repair and paint (complete) 95,00





Rear window, Scratch(es), E - Replace 0,00



Wing R R, Dent(s) and scratch(es), LI - Repair and paint (complete) 308,20

